

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21006657/DVF3E2

Date: 18/05/2022

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001461050		
Claimant Vehicle No :	SHA9479T	Insured Vehicle No :	SKV788P		
Date of Loss:	11/06/2021	Nature of Claim:	TP	Claim No:	258504

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA9479T	Engine No:	2ZR2B88179
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Chassis No:	JTDKB3FU703078157
Reg. Date:	09/01/2019 (Man. Year: 2018)	Odometer:	361039 km
Colour:	Yellow		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,229.68	5,741.42	5,488.26	48.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	1,670.00	2,430.00	59.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,329.68	7,411.42	7,918.26	51.65
+ GST 7.00/7.00% (S\$)	1,073.08	518.80	554.28	51.65
Nett Amount (S\$)	16,402.76	7,930.22	8,472.54	51.65

INSPECTION

Date of Assignment:	14/06/2021	
Date Inspected:	14/06/2021	Inspected At: Bifrost Auto Pte Ltd (sin Ming) (HQ) Blk 9 Sector C, #01-42 Sin Ming Industrial Estate Singapore 575644
Estimated Period of Repair:	6.0 days	

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Mar 2022)
Parts:	144	TOYOTA PRIUS 1.8 5DR HATCHBACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA9479T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TRUNK LID COVER	Bent	1,126.60 FL	*1,126.60 FL
2	1		*REAR TRUNK LID LOCK	Serviceable	457.90 FL	*- FL
3	1		*REAR TRUNK LID COVER TRIM BOARD	Not Necessary	254.40 FL	*- FL
4	1		*BOOT LID TRIMBOARD, CENTRE	Not Necessary	159.60 FL	*- FL
5	1		*BOOT LID TRIMBOARD SIDE (LH)	Not Necessary	92.50 FL	*- FL
6	1		*BOOT LID TRIMBOARD REAR	Not Necessary	124.80 FL	*- FL
7	1		*GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	Broken	896.30 FL	*896.30 FL
8	1		*REAR TRUNK LID LOGO (PRIUS)	Necessary	60.80 FL	*60.80 FL
9	1		*REAR TRUNK LID LOGO (HYBRID)	Necessary	52.40 FL	*52.40 FL
10	1		*REAR TRUNK LID LOGO (TOYOTA STAR)	Necessary	52.90 FL	*52.90 FL
11	1		*REAR BUMPER	Dented / Cracked	458.60 FL	*458.60 FL
12	1		*REAR BUMPER RE-INFORCEMENT	Bent	318.80 FL	*318.80 FL
13	1		*REAR BUMPER LOWER COVER	Distorted / Cut	552.60 FL	*552.60 FL
14	1		*REAR BUMPER SIDE RETAINER	Serviceable	112.70 FL	*- FL
15	1		*REAR BUMPER TOWING COVER	Dislodged	82.70 FL	*82.70 FL
16	1		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
17	1		*REAR BUMPER SIDE CLIP	Not Necessary	25.00 FL	*- FL
18	1		*REAR BUMPER UPPER STOPPER (LH)	Serviceable	76.40 FL	*- FL
19	1		*SEAL, REAR BUMPER SIDE, RH	Dislodged	148.40 FL	*148.40 FL
20	1		*REAR BUMPER UNDER SIDE COVER (RH)	Not Necessary	232.00 FL	*- FL
21	1		*ARM SUB-ASSY, REAR BUMPER (RH)	Not Necessary	139.60 FL	*- FL
22	1		*REAR BUMPER REVERSE SENSOR	Damaged	235.70 FN	*135.70 F
23	1		*TAIL LAMP ASSY (UPPER) (RH)	Mtg Cracked	557.90 FL	*557.90 FL
24	1		*TAIL LAMP ASSY (LOWER) (RH)	Cracked	548.40 FL	*548.40 FL
25	1		*TAIL LAMP QUARTER PANEL	Dented	216.00 FL	*216.00 FL
26	1		*TAIL LAMP SIDE COVER	Serviceable	256.00 FL	*- FL
27	1		*REAR END PANEL	Dented	602.10 FL	*602.10 FL
28	1		*REAR END PANEL GARNISH	Not Necessary	165.80 FL	*- FL
29	1		*REAR WIRING ASSY	Not Necessary	582.40 FL	*- FL
30	1		*REAR SPARE TYRE PANEL	Not Necessary	667.70 FL	*- FL
31	1		*REAR FIBER TOOL BOX TRIM (LH)	Not Necessary	598.00 FL	*- FL
32	1		*REAR FIBER TOOL BOX CENTER	Not Necessary	186.20 FL	*- FL
33	1		*SPARE TYRE LOCK NUT	Not Necessary	88.40 FL	*- FL
34	1		*SPARE TYRE LOCK NUT BRACKET	Not Necessary	113.50 FL	*- FL
35	1		*SPARE TYRE SIDE PANEL (LH)	Not Necessary	287.30 FL	*- FL
36	1		*REAR EXHAUST PIPE RH	Not Necessary	1,163.40 FL	*- FL
37	1		*REAR EXHAUST PIPE HANGER	Not Necessary	40.70 FL	*- FL
38	1		*REAR EXHAUST PIPE INSULATOR	Not Necessary	314.60 FL	*- FL
39	1		*REAR FENDER, RH	Dented	836.70 FL	*836.70 FL
40	1		*REAR FENDER SHIELD (LH)	Not Necessary	174.20 FL	*- FL
41	1		*REAR FENDER AIR DUCT	Deformed	165.10 FL	*165.10 FL
42	1		*REAR TRUNK LOWER W/S MOULDING	Necessary	180.00 FS	*180.00 FS
43	1		*REAR LOWER W/S SEALANT	Necessary	46.00 FS	*46.00 FS
44	1		*REAR WINDSCREEN MOULDING	Necessary	160.00 FS	*160.00 FS
45	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
46	1		*REAR BUMPER ADVERTISEMENT	Necessary	100.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR FENDER ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.						
Sub Total (S\$)					13,879.10	7,416.00
- List Item Discount on L Items 20.00/25.00% (S\$)					2,602.28	1,674.58
- Nett Item Discount on N Items 20.00/0.00% (S\$)					47.14	0.00
Total Parts (S\$)					11,229.68	5,741.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,400.00	700.00
2	SPRAY PAINTING CHARGE	New	1,200.00	700.00
3	WIRING CHARGE	New	100.00	30.00
4	TUFF KOTE	New	100.00	40.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE / REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE / REFIX REAR WINDSCREEN GLASS	New	240.00	80.00
8	REMOVE / REFIX REVERSE SENSOR	New	120.00	40.00
9	REMOVE / REFIX FUEL TANK	New	80.00	0.00
10	REMOVE / REFIX EXHAUST PIPE	New	80.00	0.00
11	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (\$\$)			4,100.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >