

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CC6/AIG21006658/APA3Q2  
**Date:** 18/08/2021

**REFERENCE**

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 7210006124   |
| <b>Claimant Vehicle No :</b> | SMZ5139K                             | <b>Insured Vehicle No :</b> | GBF7468H     |
| Date of Loss:                | 10/06/2021                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 5550324478SG |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |              |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No:                     | <b>SMZ5139K</b>                   | Engine No:  | 2ZR2L02899   |
| Make & Model:               | TOYOTA NOAH HYBRID, 1.8 X CVT (A) | Chassis No: | ZWR800480372 |
| Reg. Date:                  | 29/04/2021 (Man. Year: 2020)      | Odometer:   | 11617 km     |
| Colour:                     | Silver                            |             |              |
| Engine Capacity:            | 1797 cc                           |             |              |
| Market Value/New Car Price: | N/A                               |             |              |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |              |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 195/65 R15    | Rear Tyre Size:  | 195/65 R15    |
| Front Left Side:  | Yokohama 6 mm | Rear Left Side:  | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 17,195.75         | 9,500.52          | 7,695.23          | 44.75         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 5,390.00          | 2,630.00          | 2,760.00          | 51.21         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>22,585.75</b>  | <b>12,130.52</b>  | <b>10,455.23</b>  | <b>46.29</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>9,700.00</b>   |                   |               |

|                                                 |                  |                  |                  |              |
|-------------------------------------------------|------------------|------------------|------------------|--------------|
| (S\$)                                           | 22,585.75        | 9,700.00         | 12,885.75        | 57.05        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 1,581.00         | 679.00           | 902.00           | 57.05        |
| <b>Nett Amount (S\$)</b>                        | <b>24,166.75</b> | <b>10,379.00</b> | <b>13,787.75</b> | <b>57.05</b> |
| <b>+ Loss of Use (8.0 x S\$80.00/day) (S\$)</b> |                  | 640.00           |                  |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                  | 7.45             |                  |              |
| <b>Nett Liability (S\$)</b>                     |                  | <b>11,026.45</b> |                  |              |

INSPECTION

Date of Assignment: 11/06/2021

Date Inspected: 11/06/2021

Inspected At:

MG Solution Pte Ltd (HQ)  
 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre  
 Singapore 415933

Estimated Period of Repair: 7.0 days

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition                  | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------------|----------------------------|-------------|--------------|
| 1   | 1   |          | *TAILGATE                             | Distorted                  | 2,080.50 FL | *1,807.00 FL |
| 2   | 1   |          | *TAILGATE LOGO                        | Necessary                  | 85.00 FL    | *85.00 FL    |
| 3   | 1   |          | *TAILGATE EMBLEM HYBRID SYNERGY DRIVE | Necessary                  | 82.50 FL    | *82.50 FL    |
| 4   | 2   |          | *TAILGATE HINGE                       | Not Necessary              | 260.00 FL   | *- FL        |
| 5   | 2   |          | *TAILGATE DAMPER                      | Not Necessary              | 460.00 FL   | *- FL        |
| 6   | 1   |          | *TAILGATE LOCK                        | Damaged                    | 480.00 FL   | *368.00 FL   |
| 7   | 1   |          | *TAILGATE LOCK CATCH                  | Not Necessary              | 90.00 FL    | *- FL        |
| 8   | 1   |          | *TAILGATE INNER BOARD TRIM            | Cracked                    | 766.20 FL   | *495.00 FL   |
| 9   | 1   |          | *TAILGATE WEATHERSTRIP                | Cut                        | 330.00 FL   | *330.00 FL   |
| 10  | 1   |          | *TAILGATE INNER HANDLE                | Not Necessary              | 90.00 FL    | *- FL        |
| 11  | 1   |          | *REAR NUMBER PLATE CHROME             | Cracked                    | 866.30 FL   | *581.00 FL   |
| 12  | 1   |          | *REAR WINDSCREEN                      | Shattered                  | 1,655.30 FL | *1,350.00 FL |
| 13  | 1   |          | *REAR WINDSCREEN MOULDING             | Necessary                  | 190.00 FL   | *190.00 FL   |
| 14  | 1   |          | *TAILGATE ANTENNA LOCK                | Damaged                    | 210.00 FL   | *210.00 FL   |
| 15  | 1   |          | *REAR BUMPER                          | Distorted                  | 822.30 FL   | *822.30 FL   |
| 16  | 2   |          | *REAR BUMPER SIDE RETAINER            | Necessary                  | 124.80 FL   | *124.80 FL   |
| 17  | 1   |          | *REAR BUMPER REFLECTOR                | Not Necessary              | 110.20 FL   | *- FL        |
| 18  | 1   |          | *REAR BUMPER TOWING COVER             | Not Necessary              | 90.00 FL    | *- FL        |
| 19  | 2   |          | *REAR CORNER BUMPER                   | Deformed                   | 640.00 FL   | *640.00 FL   |
| 20  | 2   |          | *REAR CORNER BUMPER RETAINER          | Not Necessary              | 206.40 FL   | *- FL        |
| 21  | 2   |          | *REAR BUMPER REVERSE SENSOR           | Damaged                    | 382.95 FS   | *200.00 FS   |
| 22  | 2   |          | *TAILLAMP                             | Cut                        | 1,711.20 FL | *1,562.00 FL |
| 23  | 2   |          | *REAR FENDER                          | Repair                     | 3,667.00 FL | *- FL        |
| 24  | 2   |          | *REAR FENDER INNER TRIM               | N/S Cracked / O/S Deformed | 1,599.00 FL | *1,362.00 FL |
| 25  | 1   |          | *REAR END PANEL                       | Dented                     | 666.50 FL   | *666.50 FL   |
| 26  | 1   |          | *REAR END PANEL TOP GARNISH           | Cracked                    | 288.90 FL   | *288.90 FL   |
| 27  | 1   |          | *REAR FLOOR PANEL                     | Repair                     | 912.30 FL   | *- FL        |
| 28  | 1   |          | *REAR FLOOR PANEL TOP BOARD           | Deformed                   | 820.30 FL   | *691.00 FL   |
| 29  | 1   |          | *REAR FLOOR PANEL MAT                 | Not Necessary              | 680.30 FL   | *- FL        |
| 30  | 1   |          | *TOOLS COVER                          | Deformed                   | 144.70 FL   | *144.70 FL   |
| 31  | 1   |          | *REAR EXHAUST PIPE                    | Not Necessary              | 980.70 FL   | *- FL        |
| 32  | 1   |          | *REAR NUMBER PLATE                    | Cracked                    | 50.00 FS    | *50.00 FS    |
| 33  | 1   |          | *SET TAILGATE INNER BOARD CLIPS       | Necessary                  | 20.00 FS    | *20.00 FS    |
| 34  | 1   |          | *TAILGATE WINDSCREEN SOLAR FILM       | Necessary                  | 350.00 FS   | *200.00 FS   |
| 35  | 1   |          | *TAILGATE WINDSCREEN SEALANT          | Necessary                  | 100.00 FS   | *60.00 FS    |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                       | Condition     | Repairer's | Amount    |
|-----|-----|----------|-----------------------------------|---------------|------------|-----------|
| 36  | 1   |          | *SET REAR BUMPER CLIP             | Necessary     | 20.00 FS   | *20.00 FS |
| 37  | 1   |          | *SET REAR FENDER INNER TRIM CLIPS | Necessary     | 20.00 FS   | *20.00 FS |
| 38  | 1   |          | *REAR QUARTER GLASS SEALANT       | Not Necessary | 100.00 FS  | *- FS     |
| 39  | 1   |          | *SET REAR END PANEL GARNISH CLIP  | Necessary     | 20.00 FS   | *20.00 FS |
| 40  | 1   |          | *REAR END PANEL SEALANT           | Necessary     | 150.00 FS  | *60.00 FS |
| 41  | 1   |          | *REAR FLOOR PANEL SEALANT         | Not Necessary | 150.00 FS  | *- FS     |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                           |                  |                  |
|-----------------------------------------------------------|------------------|------------------|
| <b>Sub Total (S\$)</b>                                    | <b>22,473.35</b> | <b>12,450.70</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (S\$)</b> | 5,277.60         | 2,950.18         |
| <b>Total Parts (S\$)</b>                                  | <b>17,195.75</b> | <b>9,500.52</b>  |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                          | Lab.Type | Repairer's      | Amount          |
|--------------------------------|------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |                                                      |          |                 |                 |
| 1                              | TO PANEL BEAT,REMOVE AND REPLACE PARTS               | New      | 2,000.00        | 1,000.00        |
| 2                              | TO SPRAY PAINT AFFECTED AREA                         | New      | 2,000.00        | 1,200.00        |
| 3                              | TUFF COAT                                            | New      | 250.00          | 60.00           |
| 4                              | WIRING CHECK                                         | New      | 120.00          | 30.00           |
| 5                              | TO CONDUCT WATER LEAKAGE TEST                        | New      | 100.00          | 0.00            |
| 6                              | TO TRANSFER TAIL GATE MECHANISM                      | New      | 180.00          | 80.00           |
| 7                              | LABOUR TO REMOVE AND REFIT WINDSCREEN                | New      | 120.00          | 120.00          |
| 8                              | LABOUR TO REMOVE AND REFIT PHV STICKER               | New      | 60.00           | 40.00           |
| 9                              | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING | New      | 80.00           | 50.00           |
| 10                             | REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING | New      | 80.00           | 50.00           |
| 11                             | REMOVE AND REFIX CAR BATTERY                         | New      | 100.00          | 0.00            |
| 12                             | REMOVE AND REFIX AIRCON COOLER ASSY                  | New      | 120.00          | 0.00            |
| 13                             | REMOVE AND REFIX REAR EXHAUST PIPE                   | New      | 180.00          | 0.00            |
| <b>Gross Labour Cost (S\$)</b> |                                                      |          | <b>5,390.00</b> | <b>2,630.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >