

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21006661/Vtce2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA Date: 23/06/2021 **TOWERSINGAPORE 068811** ATTN: NG STACEY Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SFU 3338A SJL 7753H Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. S1M03BRO Excess (\$) 0.00 **Assign Date** NG STACEY 14/06/2021 Assign From **Vehicle Particulars & Condition** 2. TOYOTA WISH 1.8 (A) Make & Model 1794 C.C HIDDEN 2008 Engine No. Year of Reg. JTDER12W703001244 SILVER Chassis No. Colour Odometer 235991 KM Steering IN ORDER **IN ORDER** STANDARD ALLOY RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195/65 R15 CONTINENTAL 5 mm CONTINENTAL L/H Front Tyre 195/65 R15 5 mm 195/65 R15 CONTINENTAL R/H Rear Tyre 5 mm CONTINENTAL L/H Rear Tyre 195/65 R15 5 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. 5. **General Information** 11/06/2021 14/06/2021 (02:00 PM) Inspect Date / Time Accident Date **GARAGE 13 PTE LTD** Survey held at 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE. 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

Report Ref No. CS3/ASM21006661/Vtce2

Estimate Days of Repair

Inspected By

5b.

THEVAN THOMAS KARTHIKESAVAN

ESTIMATED NORMAL PERIOD FOR REPAIR:

L

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

5 Working Days