

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006663/UPS3Q2**Date:** 11/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100283240-09
Claimant Vehicle No :	JNR5466	Insured Vehicle No :	GBC3257S
Date of Loss:	30/05/2021	Nature of Claim:	TP
		Claim No:	8461113677SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	JNR5466	Engine No:	G3A1EE027027
Make & Model:	HONDA ACCORD, 1.6 (M)	Chassis No:	PMYKG0550C0027027
Reg. Date:	25/06/2012 (Man. Year: 2012)	Odometer:	0 km
Colour:	Multi-colour		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70-90-17	Rear Tyre Size:	90-80-17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,918.30	2,732.10	2,186.20	44.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	915.00	535.00	380.00	41.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,833.30	3,267.10	2,566.20	43.99
Approved Total (Overridden) (S\$)		1,300.00		
Nett Amount (S\$)	5,833.30	1,300.00	4,533.30	77.71
+ Loss of Use (5.0 x S\$20.00/day) (S\$)		100.00		
		(S\$)		
		1,400.00		
Liabe Amount (80.00%) (S\$)		1,120.00		
Global Sum Settlement (S\$)		1,120.00		

INSPECTION

Date of Assignment:	14/06/2021	
Date Inspected:	15/06/2021	Inspected At:
		Erofia Motor Trading Pte Ltd (KAKI BUKIT)
		1 KAKI BUKIT AVE 6 #02-62
		Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK TUBE ASSY	Distorted	640.00 FL	*520.00 FL
2	1		*FRONT WHEEL RIM	Warped	380.00 FL	*250.00 FL
3	1		*FORK UNDER BRACKET	Bent	185.00 FL	*185.00 FL
4	1		*FRONT RIM SHAFT	Bent	45.00 FL	*45.00 FL
5	1		*FRONT RIM BEARING	Damaged	38.00 FL	*38.00 FL
6	1		*FRONT BRAKE DISC	Bent	165.00 FL	*105.00 FL
7	1		*FRONT FAIRING INNER COVER	Cracked	175.00 FL	*175.00 FL
8	1		*HANDLE BAR	Not Necessary	88.00 FL	*- FL
9	2		*HANDLE BAR ENDS	Not Necessary	78.00 FL	*- FL
10	1		*SET HAND GRIP	Not Necessary	75.00 FL	*- FL
11	1		*HANDLE BAR INNER BRACKET	Not Necessary	88.00 FL	*- FL
12	1		*SIDE MIRRORS	O/S Cut	110.00 FL	*48.00 FL
13	1		*BRAKE LEVER (O/S)	Scratched	42.00 FL	*35.00 FL
14	2		*FRONT SIGNALS	Cracked	160.00 FL	*160.00 FL
15	1		*FRONT SIGNAL LOWER GARNISH	Cracked	105.00 FL	*105.00 FL
16	1		*HEADLAMP	Cracked	225.00 FL	*180.00 FL
17	1		*SET FAIRING ASSY	Broken	525.00 FL	*450.00 FL
18	1		*FRONT FOOTREST BRACKET	Bent	65.00 FL	*65.00 FL
19	1		*FRONT FOOTREST RUBBERS	O/S Torn	70.00 FL	*30.00 FL
20	1		*BRAKE PEDAL	Repair	42.00 FL	*- FL
21	1		*REAR FOOTREST	O/S Cut	80.00 FL	*30.00 FL
22	1		*REAR FOOTREST BRACKETS	O/S Cracked	156.00 FL	*68.00 FL
23	1		*EXHAUST ASSY	Repair	585.00 FL	*- FL
24	1		*EXHAUST PROTECTOR -CHROME	Bent	75.00 FL	*75.00 FL
25	1		*EXHAUST PROTECTOR -BLACK	Bent	55.00 FL	*55.00 FL
26	1		*RADIATOR	Cut / Bent	485.00 FL	*350.00 FL
27	1		*SPARE TANK	Not Necessary	105.00 FL	*- FL
28	1		*BASKET	Not Necessary	85.00 FL	*- FL
29	1		*SET NUMBER PLATE	Frt Necessary	28.00 FS	*10.00 FS
30	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
31	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
32	1		*SET STEERING CONE	Necessary	90.00 FS	*50.00 FS
33	1		*FRONT TYRE	Serviceable	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,411.00	3,029.00
- List Item Discount on L Items 10.00/10.00% (\$)	492.70	296.90
Total Parts (\$)	4,918.30	2,732.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE (LOD)	New	35.00	35.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO PROVIDE LABOUR	New	420.00	300.00
4	TO REPAIR BODY FRAME	New	380.00	200.00
Gross Labour Cost (\$\$)			915.00	535.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >