

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC6/III21006665/UGS3Q2

Date:

04/10/2021

REFERENCE

| | | | |
|------------------------------|---------------------------------------|-----------------------------|------------------|
| Handling Insurer: | India International Insurance Pte Ltd | Policy No: | D19MFL0005549_01 |
| Claimant Vehicle No : | SLU7340U | Insured Vehicle No : | GBH1454B |
| Date of Loss: | 13/06/2021 | Nature of Claim: | TP |
| | | Claim No: | MFL2021D0002543 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-------------------------------------|-------------|-------------------|
| Reg No: | SLU7340U | | |
| Make & Model: | TOYOTA SIENNA, 1.5 CVT ELEGANCE (A) | Engine No: | 2NRX230527 |
| Reg. Date: | 12/12/2017 (Man. Year: 2017) | Chassis No: | MHFZ28H3500045163 |
| Colour: | Black | Odometer: | 76781 km |
| Engine Capacity: | 1496 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition: | | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 195/50 R16 | Rear Tyre Size: | 195/50 R16 |
| Front Left Side: | Bridgestone 8 mm | Rear Left Side: | Bridgestone 8 mm |
| Front Right Side: | Bridgestone 8 mm | Rear Right Side: | Bridgestone 8 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 5,996.47 | 4,887.45 | 1,109.02 | 18.49 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,650.00 | 1,510.00 | 1,140.00 | 43.02 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 8,646.47 | 6,397.45 | 2,249.02 | 26.01 |
| Global Sum Settlement (S\$) | | 0.00 | | |

INSPECTION

Date of Assignment: 14/06/2021

Date Inspected: 14/06/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Hup Motor Trading & Service (HQ)
Blk 9004 Tampines Street 93, #01-120
Singapore 528838

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | |
|---|--|
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 04 Oct 2021) |
| Parts: M1-MPV | TOYOTA SIENNA 1.5 CVT ELEGANCE (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: Repairer's | (Price-denominated Standard List) |
| Print Code: (Unsubmitted, no print-code for SLU7340U) | |
| Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------------|------------------|-------------|--------------|
| 1 | 1 | | *FRONT O/S FENDER | Badly Dented | 713.20 FL | *713.20 FL |
| 2 | 1 | | *FRONT O/S FENDER INNER SHIELD | Distorted / Torn | 216.70 FL | *216.70 FL |
| 3 | 8 | | *FRONT O/S FENDER INNER SHIELD CLIPS | Necessary | 34.40 FL | *34.40 FL |
| 4 | 10 | | *FRONTBONNET INSULATOR CLIPS | Not Necessary | 48.00 FL | *- FL |
| 5 | 1 | | *O/S HEAD LAMP ASSY | Broken | 3,435.90 FL | *3,049.10 FL |
| 6 | 1 | | *O/S HEAD LAMP BRACKET | Not Necessary | 24.00 FL | *- FL |
| 7 | 1 | | *FRONT BUMPER | Distorted | 599.60 FL | *599.60 FL |
| 8 | 16 | | *FRONT BUMPER TOP & LOW CLIPS | Necessary | 68.80 FL | *68.80 FL |
| 9 | 1 | | *FRONT BUMPER REINFORCEMENT | Bent | 383.90 FL | *383.90 FL |
| 10 | 1 | | *FRONT BUMPER LOWER RUBBER | Not Necessary | 193.30 FL | *- FL |
| 11 | 8 | | *FRONT BUMPER LOWER RUBBER CLIPS | Not Necessary | 35.40 FL | *- FL |
| 12 | 1 | | *FRONT BUMPER TOP RUBBER | Necessary | 65.90 FL | *65.90 FL |
| 13 | 6 | | *FRONT BUMPER TOP RUBBER CLIPS | Not Necessary | 25.80 FL | *- FL |
| 14 | 1 | | *FRONT BUMPER O/S FOG LAMP ASSY | Cracked | 458.10 FL | *458.10 FL |
| 15 | 1 | | *FRONT BUMPER O/S FOG LAMP GARNISH | Distorted | 108.50 FL | *108.50 FL |
| 16 | 1 | | *FRONT BUMPER O/S SIDE REFLECTOR | Cracked | 73.90 FL | *73.90 FL |
| 17 | 1 | | *FRONT BUMPER O/S TOP RETAINER | Bent | 54.90 FL | *54.90 FL |
| 18 | 1 | | *FRONT GRILLE | Distorted | 689.60 FL | *689.60 FL |
| 19 | 1 | | *FRONT GRILLE LOGO | Not Necessary | 80.20 FL | *- FL |
| 20 | 1 | | *FRONT GRILLE MOULDING | Not Necessary | 154.20 FL | *- FL |
| 21 | 6 | | *FRONT GRILLE CLIPS | Not Necessary | 25.80 FL | *- FL |
| 22 | 1 | | *WASHER TANK | Serviceable | 141.40 FL | *- FL |
| 23 | 1 | | *FRONT O/S TOP PANEL | Repair | 213.50 FL | *- FL |
| 24 | 1 | | *O/S HEAD LAMP PANEL | Repair | 150.30 FL | *- FL |

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)**7,995.30****6,516.60****- List Item Discount on L Items 25.00/25.00% (\$\$)**

1,998.83

1,629.15

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount | |
|-----|-----|----------|-------------|-----------|---------------------------|-----------------|-----------------|
| | | | | | Total Parts (\$\$) | 5,996.47 | 4,887.45 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|---|----------|--------------------------------|-----------------|
| Labour Items | | | | |
| 1 | TO WIRING CHECK UP & ADJUST HEADLIGHT ALIGNMENT | New | 50.00 | 20.00 |
| 2 | TO CHECK & ADJUST FRONT WHEEL ALIGNMENT & BALANCING | New | 120.00 | 60.00 |
| 3 | TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS | New | 80.00 | 0.00 |
| 4 | LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK,STRAIGHTEN & KNOCKING OUT NECESSARY PARTS ,TO WELD ,RENEW & ALIGN ABOVE PARTS TO | New | 950.00 | 550.00 |
| 5 | TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS | New | 1,450.00 | 880.00 |
| | | | Gross Labour Cost (S\$) | 2,650.00 |
| | | | | 1,510.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >