



簡福星摩哆工廠
KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12, Singapore 539147
Tel: (65) 6747 9560, 6743 5344, 6858 4361 • Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net / patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883
Tel: (65) 6481 5150 • Fax: (65) 6481 8683

TAX INVOICE

No. 50178

Business Reg. No. 221468-00E
GST Reg. No. M9-0005333-E

LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE
199555

INVOICE NO : 50178

DATE : 25-10-2021

VEHICLE NO. : XE725G
ACCIDENT DATE : 04-06-2021 10:20
THIRD PARTY REF. :

ATTN: MOTOR CLAIMS DEPT.

INVOICE COST OF REPAIRS TO VEHICLE XE725G SCANIA P 440CB 6X4MHZ 5100 CP19N

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	WOODEN DROP SIDE	3000.00
1	SAFETY BARRIER	5000.00
1	INTERNAL FATIGUE	10000.00
		18,000.00
	ADD 10 %	
		1,800.00
	TOTAL (A)	
		19,800.00
	TOTAL REPAIR COST :	
		19,800.00
	G S T % :	
		1,281.00
	EXCESS AMOUNT :	
		1,500.00
	INVOICE AMOUNT :	
		19,581.00



IN PANEL-BEATING & BODY-WORK, OUR WORKSHOP IS WELL-EQUIPPED WITH THE LATEST TECHNOLOGY --- CELETTE BENCH PULLER SYSTEM WHICH ENABLE US TO MEASURE CORRECTLY & REPAIR MANY DIFFERENT KINDS OF DAMAGES, SERIOUS DAMAGES TO THE FLOOR-BOARD CHASSIS & WHEEL-HOUSING CAN BE RESTORED BACK TO THE ACCORDING MEASUREMENT. WE ARE ABLE TO REPAIR & RESTORE ANY BADLY DAMAGED VEHICLE BACK TO ITS ORIGINAL SPECIFICATIONS TO ENSURE SAFETY WHILE DRIVING.

在钣金修理業，本廠有最精良，先進的機械，來準確測量及修理，在規格尺寸圖內，本公司有能力回復原來相符的程度。