

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

Affiliated to Federation Internationale Des Experts En Automobile					
	AIG ASIA PACIFIC	INSURANCE PTE LTD	Ref:	CS3/AIG21002700/Gvf3e2-1	
	78 SHENTON WAY AIG BUILDING SINGAPORE 0791		Date:	07/09/2021	
	ATTN: BENNIE TA	N	Code:	AIG	
1.	Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
	Insured Veh.	SKW 25C	Veh. Inspected	SLL 5550R	
	Policy No.	2100504067	Coverage (\$)	0.00	
	Claim No.	5871451378SG	Excess (\$)	0.00	
	Assign From	BENNIE TAN	Assign Date	14/06/2021	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA ODYSSEY 2.4	c.c	2356	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	JHMRC1890GC209959	Colour	WHITE	
	Odometer	124517 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	215/55 R17	TOYO	6 mm	
	L/H Front Tyre	215/55 R17	тоуо	6 mm	
	R/H Rear Tyre	215/55 R17	TOYO	6 mm	
	L/H Rear Tyre	215/55 R17	TOYO	6 mm	
4.	Description of Damages				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
	REPAIR CONDITION SEE DETAILS.				
5.	General Information				
	Accident Date	19/02/2021	Inspection Date	05/08/2021	
	Survey held at	blk 916 hougang ave 9			
	Repairer	ENG SOON PAINTING SVC			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			
	l				