

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC6/AIG21006669/APS3Q2

Date:

05/10/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1900103624

Claimant Vehicle No : SJK7136U**Insured Vehicle No :**

SFC9393U

Date of Loss: 11/06/2021

Nature of Claim:

TP

Claim No:

5732570349SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJK7136U**

Make & Model: HONDA AIRWAVE, 1.5 M (A)

Engine No:

L15A5207467

Reg. Date: 30/10/2008 (Man. Year: 2008)

Chassis No:

GJ11306125

Colour: Blue

Odometer:

222611 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Rear Tyre Size:

195/55 R15

Front Left Side: Tourador 6 mm

Rear Left Side:

Tourador 6 mm

Front Right Side: Tourador 6 mm

Rear Right Side:

Tourador 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,906.16	2,265.52	1,640.64	42.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,080.00	830.00	250.00	23.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,986.16	3,095.52	1,890.64	37.92
Approved Total (Overridden) (S\$)		2,450.00		

(S\$)	4,986.16	2,450.00	2,536.16	50.86
+ GST 7.00/7.00% (S\$)	349.03	171.50	177.53	50.86
Nett Amount (S\$)	5,335.19	2,621.50	2,713.69	50.86
+ Loss of Use (5.0 x S\$70.00/day) (S\$)		350.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		3,007.95		
Global Sum Settlement (S\$)		3,000.00		

INSPECTION

Date of Assignment: 14/06/2021

Date Inspected: 14/06/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Ryder Auto Pte Ltd (HQ)
 2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit
 Singapore 417921

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	726.70 FL	*726.70 FL
2	1		*FRONT BUMPER N/S RETAINER	Necessary	86.70 FL	*86.70 FL
3	1		*FRONT BUMPER GRILLE (LOWER)	Not Necessary	496.60 FL	*- FL
4	1		*FRONT BUMPER N/S FOG LAMP	Not Necessary	316.70 FL	*- FL
5	1		*FRONT GRILLE	Cracked	436.70 FL	*436.70 FL
6	1		*FRONT N/S HEAD-LAMP	Cracked	896.80 FL	*896.80 FL
7	1		*FRONT O/S HEAD LAMP RETAINER	Not Necessary	65.70 FL	*- FL
8	1		*FRONT N/S FENDER	Not Necessary	796.80 FL	*- FL
9	10		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
10	1		*FRONT BUMPER LOWER LIP	Cracked	600.00 FS	*500.00 FS
11	6		*FRONT GRILLE CLIPS	Necessary	18.00 FS	*18.00 FS
12	1		*SET FRONT HEAD LAMP CHROME	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,670.70	2,694.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	764.54	429.38
Total Parts (\$\$)	3,906.16	2,265.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE DAMAGED PARTS ,STRAIGHTEN & WELDING	New	600.00	400.00
2	TO SPRAY PAINTING	New	450.00	400.00
3	TO CHECK WIRING	New	30.00	30.00
Gross Labour Cost (\$\$)			1,080.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >