



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2200331

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 14/01/2022
Reference CC4/LPC21006675/Ugs3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLC 5080C
Insured Veh. XD 6760U
Claim No. 21/21/21/VC00/024652
Policy No. Z/21/VC00/111107
Accident Date 11/06/2021
Inspection Date 14/06/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21006675/Ugs3q2 Date: 14/01/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 6760U	Veh. Inspected	SLC 5080C	
Policy No.	Z/21/VC00/111107	Coverage (\$)	0.00	
Claim No.	21/21/21/VC00/024652	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	14/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN SPORTSVAN (A)	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WVWZZZAUZGW581008	Colour	BLUE	
Odometer	100807 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	CONTINENTAL	7 mm	
L/H Front Tyre	225/40 R18	CONTINENTAL	7 mm	
R/H Rear Tyre	225/40 R18	CONTINENTAL	7 mm	
L/H Rear Tyre	225/40 R18	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/06/2021	Inspection Date	14/06/2021	
Survey held at	NPH AUTO SERVICE BLK 9005 TAMPINES STREET 93 #01-246/254 SINGAPORE 528839			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 5080C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR WINDSCREEN RUBBER MOULDING	NECESSARY	226.00	110.90
1	REAR BOOT	BADLY DENTED	1,771.00	1,771.00
1	REAR BOOT CENTER LOGO WOTH LOCK HANDLE	SCRATCHED	110.00	110.00
1	REAR BOOT 230TSI EMBLEM	NECESSARY	88.00	86.00
1	REAR LAMP ASSY O/S	CRACKED	277.00	277.00
1	REAR BUMPER	DENTED	1,056.00	1,056.00
3	REAR BUMPER PARKING SENSOR @\$199.00	SHORTED (1 PCS ONLY)	597.00	199.00
1	REAR BUMPER LOWER SPOILER	NOT NECESSARY	388.00	-
1	REAR BUMPER TOP SUPPORT FIBRE ENFORCEMENT	CRACKED	80.00	80.00
1	REAR BUMPER REINFORCEMENT	BENT	528.00	495.20
1	REAR BUMPER TOWING HOOK COVER	NOT NECESSARY	35.00	-
1	REAR BUMPER REFLECTOR LAMP	NOT NECESSARY	75.00	-
2	REAR BUMPER SIDE RETAINER L&R @\$60.00	NOT NECESSARY	120.00	-
1	REAR BOOT RUBBER	TWISTED	299.00	295.00
1	REAR BOOT LAMP O/S	CRACKED	244.00	244.00
1	REAR LAMP CENTER PANEL	TO REPAIR SEE LABOUR	627.00	-
1	REAR LAMP PANEL INNER RUBBER GARNISH	NOT NECESSARY	173.00	-
2	REAR NUMBER PLATE LAMP L&R @\$80.00	NOT NECESSARY	160.00	-
	LESS 10% DISCOUNT		-685.40	-472.41
			6,168.60	4,251.69
<u>SPECIAL NETT ITEMS</u>				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	40.00	40.00
1	REAR NUMBER PLATE W/CASING (SN)	SCRATCHED	45.00	40.00
			85.00	80.00
<u>LABOUR</u>				
	REMOVE & INSTALL REAR WINDSCREEN.		150.00	120.00
	REMOVE & INSTALL REAR CARPET.		100.00	80.00
	RESET PARKING SENSOR .		120.00	50.00
	CHECK WIRING SYSTEM.		25.00	20.00

Report Ref No. CC4/LPC21006675/Ugs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & INSTALL R/BOOT,R/LAMP ,R/BUMPER ,CUT OUT & RENEW R/LAMP CENTER PANEL,KNOCK SPARE TYRE PANEL AND RESTRAIGHTEN BOFY & CHASSIS .INCLUSIVE OF THE REPAIR OF REAR LAMP CENTER PANEL . SPRAY PAINTING.		1,100.00	700.00
			1,000.00	850.00
			2,495.00	1,820.00
GRAND TOTAL			8,748.60	6,151.69
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,900.00

Report Ref No. CC4/LPC21006675/Ugs3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLC 5080C

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLC 5080C

RE-INSPECTION

