



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGM 900B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	30.00	30.00
1	COVER, FR BUMPER (SN)	DEFORMED	667.60	667.60
1	SUPPORT, FR BUMPER (SN)	BENT	99.20	99.20
10	CLIPS (SN)	NECESSARY	41.00	41.00
1	FENDER SUB-ASSY, FR (SN)	DENTED	1,259.40	1,259.40
1	SHIELD SUB-ASSY, (SN)	NOT NECESSARY	261.60	-
2	CLIP (SN)	NOT NECESSARY	3.60	-
1	PANEL SUB-ASSY, FR (SN)	TO REPAIR SEE LABOUR	2,101.90	-
1	UNIT, HEADLAMP (SN)	CRACKED	3,835.60	3,835.60
			8,299.90	5,932.80
	<u>LABOUR</u>			
	CHECK LIGHTING & WIRING SYSTEM.		122.40	122.40
	TO RESET ECU AND REPROGRAMME.		180.00	180.00
	REPLACE RH FRT ACCIDENT DAMAGED PARTS.		2,160.00	1,440.00
	STRAIGHTEN & ALIGN RH FRT ACCIDENT AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY, FR.			
	RESPRAY JOB ON RH FRT ACCIDENT AFFECTED AREAS.		2,360.00	2,065.00
			4,822.40	3,807.40
GRAND TOTAL			13,122.30	9,740.20
RECOMMENDED COST OF REPAIRS				9,740.20

Report Ref No. CS/SMR21006676/Auf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.