

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21006683/KUCE2

Date: 18/08/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00175162000
Claimant Vehicle No: SKD1601H Insured Vehicle No: SJR3413J
Date of Loss: 11/06/2021 Nature of Claim: TP Claim No: SNM21D203331/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKD1601H
Make & Model: MERCEDES-BENZ C180, 1.6 (A) Engine No: 27191031348166
Reg. Date: 01/11/2011 (Man. Year: 2011) Chassis No: WDD2040452A610992
Colour: White Odometer: 197033 km
Engine Capacity: 1597 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17
Front Left Side: Continental 8 mm Rear Left Side: Continental 8 mm
Front Right Side: Continental 8 mm Rear Right Side: Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,940.00	3,345.00	1,595.00	32.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,060.09	790.28	269.81	25.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,000.09	4,135.28	1,864.81	31.08
Approved Total (Overridden) (S\$)		3,300.00		
(S\$)	6,000.09	3,300.00	2,700.09	45.00
+ GST 7.00/7.00% (S\$)	420.01	231.00	189.01	45.00
Nett Amount (S\$)	6,420.10	3,531.00	2,889.10	45.00

INSPECTION

Date of Assignment: 14/06/2021
Date Inspected: 17/06/2021 Inspected At: S & H Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #07-02, Sin Ming AutoCity
Singapore 575722
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Aug 2021)
Parts:	M1-COUPE	MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKD1601H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER COVER	Buckled	780.00 F	*780.00 F
2	1		*L/R BUMPER GUIDE	Cracked	40.00 F	*40.00 F
3	1		*CTR REAR BUMPER MLDG	Necessary	125.00 F	*125.00 F
4	1		*L/R BUMPER MOULDING	Necessary	95.00 F	*95.00 F
5	1		*R/R BUMPER MOULDING	Necessary	95.00 F	*95.00 F
6	1		*L/R INN BUMPER BRKT	Repair	65.00 F	*- F
7	1		*REAR BUMPER C-MEMBER	Bent	450.00 F	*450.00 F
8	1		*L/R INN PARKING SENS	Shorted	230.00 F	*230.00 F
9	1		*R/R INN PARKING SENS	Shorted	230.00 F	*230.00 F
10	1		*L/R OUT PARKING SENS	Serviceable	230.00 F	*- F
11	1		*BOOTLID / TAILGATE	Bent	950.00 F	*950.00 F
12	1		*STAR EMBLEM	Necessary	45.00 F	*45.00 F
13	1		*REAR BADGE	Necessary	60.00 F	*60.00 F
14	1		*BADGE KOMPRESSOR	Necessary	80.00 F	*80.00 F
15	1		*BOOT BADGE C180 (NPA)	Necessary	0.00 F	*- F
16	1		*BOOT CHROME MOULDING	Serviceable	140.00 F	*- F
17	1		*BOOT BADGE C&C	Necessary	65.00 F	*65.00 F
18	1		*SUNDRY	Necessary	100.00 FS	*100.00 FS
19	1		*L/F SEAT HEADREST	Repair	580.00 F	*- F
20	1		*R/F SEAT HEADREST	Repair	580.00 F	*- F

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	4,940.00	3,345.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ECU DIAGNOSTIC	New	150.00	120.00
2	ELECTRICAL WORK	New	15.00	15.00
3	TUFF KOTE	New	80.00	30.00
4	70.0 WU X 42.00 SGD/H	New	294.00	176.40
5	LABOUR COST 82.0 WU X 42.00 SGD/H	New	344.40	285.60
6	MATERIAL COST	New	176.69	163.28
Gross Labour Cost (S\$)			1,060.09	790.28

Report was unsubmitted during this print-out.

< END OF ESTIMATES >