

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21006684/KQC2**Date:** 20/08/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00010242100
Claimant Vehicle No :	SMM6026P	Insured Vehicle No :	XE5782H
Date of Loss:	10/06/2021	Nature of Claim:	TP
		Claim No:	SNM21D203349/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM6026P	Engine No:	LEB7104614
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GP72003548
Reg. Date:	05/07/2019 (Man. Year: 2018)	Odometer:	158691 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	INTERTRAC 9 mm	Rear Left Side:	SUNWIDE 7 mm
Front Right Side:	INTERTRAC 9 mm	Rear Right Side:	SUNWIDE 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,851.80	1,980.16	4,871.64	71.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,070.00	1,930.00	1,140.00	37.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,921.80	3,910.16	6,011.64	60.59
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	9,921.80	3,100.00	6,821.80	68.76
+ GST 7.00/7.00% (S\$)	694.53	217.00	477.53	68.76
Nett Amount (S\$)	10,616.33	3,317.00	7,299.33	68.76

INSPECTION

Date of Assignment:	14/06/2021	
Date Inspected:	17/06/2021 Inspected At:	Optima Werkz Pte Ltd (HQ) 10 Ang Mo Kio Industrial Park 2A, #01-05 AMK Autopoint Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Aug 2021)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM6026P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deep Cut	921.10 FL	*921.10 FL
2	1		*REAR BUMPER SIDE BRACKET RH	Serviceable	35.60 FL	*- FL
3	1		*REAR FENDER RH	Repair	909.20 FL	*- FL
4	1		*REAR DOOR RH	Repair	843.20 FL	*- FL
5	1		*REAR DOOR PROTECTIVE STICKER RH	Not Necessary	26.90 FL	*- FL
6	1		*FRONT DOOR RH	Bent	907.60 FL	*795.30 FL
7	1		*FRONT DOOR PROTECTIVE STICKER RH	Necessary	48.30 FL	*48.30 FL
8	1		*FRONT FENDER RH	Repair	455.50 FL	*- FL
9	1		*FRONT FENDER HYBRID EMBLEM RH	Necessary	61.20 FL	*61.20 FL
10	1		*FRONT FENDER INNER LINER RH	Serviceable	109.35 FL	*- FL
11	1		*FRONT SIDE MIRROR ASSY RH	Cracked	573.20 FL	*527.50 FL
12	1		*FRONT SIDE MIRROR COVER RH	Cracked	59.30 FL	*59.30 FL
13	1		*FRONT BUMPER	Repair	975.20 FL	*- FL
14	1		*FRONT BUMPER SIDE BRACKET RH	Serviceable	48.60 FL	*- FL
15	1		*FRONT HEADLAMP RH	Serviceable	2,315.50 FL	*- FL
16	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
17	1		*FRONT FENDER INNER LINER CLIPS	Not Necessary	40.00 FS	*- FS
18	1		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
19	1		*REAR FENDER GLASS SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,509.75	2,462.70
- List Item Discount on L Items 20.00/20.00% (\$)	1,657.95	482.54
Total Parts (\$)	6,851.80	1,980.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,REPLACE,REFIX & READJUST ACCIDENT AREAS & ETC	New	1,300.00	600.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER,REAR FENDER RH,REAR DOOR RH,FRONT DOOR RH,FRONT FENDER RH,FRONT BUMPER & ETC	New	1,300.00	1,250.00
3	LABOUR CHARGES TO REMOVE & REINSTALLED FRONT & REAR DOOR RH INNER MECHANISM & ETC.TO EFFECT REPLACE OF FRONT & REAR DOOR RH	New	240.00	60.00
4	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	20.00
5	LABOUR CHARGES TO REMOVE & REFIX REAR FENDER GLASS RH,REAR FENDER GLASS SEALANT & ETC.TO EFFECT REPLACE OF REAR FENDER RH	New	150.00	0.00
Gross Labour Cost (\$\$)			3,070.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >