



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMV 6978U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET	DENTED	827.90	681.10
1	FRONT "TOYOTA" MOTIF	SERVICEABLE	86.00	-
	LESS 25% DISCOUNT		-	-170.28
			913.90	510.82
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT "CORPORATE" ADVERTISEMENT & ARTWORK (SN)	NECESSARY	300.00	180.00
			300.00	180.00
	<u>LABOUR</u>			
	LABOR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN & REPLACING PARTS ETCS.		250.00	100.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREA.		280.00	200.00
			530.00	300.00
	GRAND TOTAL		1,743.90	990.82
RECOMMENDED COST OF REPAIRS				990.82

Report Ref No. CS/AWA21006692/Uvf3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.