

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG21006694/AGA3Q2**Date:** 19/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070033584
<b>Claimant Vehicle No :</b>	SJV5082X	<b>Insured Vehicle No :</b>	GBE8394K
Date of Loss:	09/06/2021	Nature of Claim:	TP
		Claim No:	8964877622SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJV5082X</b>		
Make & Model:	MITSUBISHI LANCER, 1.5 MIVEC SPORTS AT ABS D/AB (A)	Engine No:	4A910127937
Reg. Date:	28/01/2010 (Man. Year: 2009)	Chassis No:	JMYSRCY2AAU000704
Colour:	Black	Odometer:	158925 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,054.00	1,621.10	1,432.90	46.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,620.00	870.00	750.00	46.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,674.00</b>	<b>2,491.10</b>	<b>2,182.90</b>	<b>46.70</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,000.00</b>		
<b>(S\$)</b>	4,674.00	2,000.00	2,674.00	57.21
<b>+ GST 7.00/7.00% (S\$)</b>	327.18	140.00	187.18	57.21
<b>Nett Amount (S\$)</b>	<b>5,001.18</b>	<b>2,140.00</b>	<b>2,861.18</b>	<b>57.21</b>
<b>+ Car Rental (5.0 x S\$100.00/day) (S\$)</b>		500.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>2,647.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,600.00</b>		

INSPECTION

Date of Assignment:	14/06/2021	
Date Inspected:	14/06/2021	Inspected At: New Zen Werkz Pte Ltd (HQ) Blk 3 kaki Bukit road 1 #03-04 Eunos Technolink Singapore 415935
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID NUMBER PLATE	Not Necessary	50.00 F	*- FL
2	1		*REAR BOOT LID NUMBER PLATE GARNISH	Not Necessary	115.00 F	*- FL
3	1		*REAR TAIL LAMP -RH	Cracked	385.00 F	*385.00 FL
4	4		*REAR TAIL LAMP CLIPS	Necessary	32.00 F	*10.00 FL
5	2		*REAR TAIL LAMP PANEL	Not Necessary	138.00 F	*- FL
6	1		*REAR BUMPER	Deformed	674.00 F	*674.00 FL
7	2		*REAR BUMPER SIDE BRACKET	Not Necessary	82.00 F	*- FL
8	12		*REAR BUMPER SIDE BRACKET DEVIT	Not Necessary	30.00 F	*- FL
9	1		*REAR BUMPER CENTER BEAM	Bent	215.00 F	*155.00 FL
10	10		*REAR BUMPER CLIPS	Necessary	65.00 F	*30.00 FL
11	1		*REAR BUMPER REVERSE SENSOR	Damaged	300.00 FS	*200.00 FS
12	1		*REAR BUMPER REINFORCEMENT	Dented	388.00 F	*325.00 FL
13	1		*REAR END PANEL	Repair	412.00 F	*- FL
14	1		*REAR END PANEL TOP GARNISH	Not Necessary	168.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>3,054.00</b>	<b>1,779.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$)</b>	0.00	157.90
<b>Total Parts (\$)</b>	<b>3,054.00</b>	<b>1,621.10</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIX CUSHION	New	120.00	40.00
2	TO REMOVE & REFIX REVERSE SENSOR	New	120.00	50.00
3	TUFF KOTE	New	120.00	50.00
4	TO CHECK WIRING	New	60.00	30.00
5	PANEL BEATING	New	600.00	300.00
6	SPRAY PAINTING	New	600.00	400.00
			<b>Gross Labour Cost (\$)</b>	<b>870.00</b>
			<b>1,620.00</b>	<b>870.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >