

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21006696/ATCN2**Date:** 02/11/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00086102000

**Claimant Vehicle No :** ES64G **Insured Vehicle No :** GBB8989K

Date of Loss: 14/06/2021 Nature of Claim: TP Claim No: SNM21D203376/C02/TANKW

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **ES64G**

Make & Model: LEXUS CT200H, 1.8 (A) Engine No: 2ZRR284505

Reg. Date: 12/01/2012 (Man. Year: 2011) Chassis No: JTHKD5BH702025901

Colour: Black Odometer: 395161 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,624.30	9,067.03	2,557.27	22.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,340.00	2,000.00	1,340.00	40.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>14,964.30</b>	<b>11,067.03</b>	<b>3,897.27</b>	<b>26.04</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>7,000.00</b>		
<b>(\$\$)</b>	14,964.30	7,000.00	7,964.30	53.22
<b>+ GST 7.00/7.00% (\$\$)</b>	1,047.50	490.00	557.50	53.22
<b>Nett Amount (\$\$)</b>	<b>16,011.80</b>	<b>7,490.00</b>	<b>8,521.80</b>	<b>53.22</b>

**INSPECTION**

Date of Assignment: 19/07/2021

Date Inspected: 15/06/2021 Inspected At: N-51 Automotive Pte Ltd (HQ)  
BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT  
AUTOHUB  
Singapore 417921

Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 29 Oct 2021)
<b>Parts:</b>	143	LEXUS CT200H 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for ES64G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	960.30 FL	*960.30 FL
2	2	*REAR BUMPER CORNER BRACKET L/R	Not Necessary	177.60 FL	*- FL
3	1	*REAR BUMPER INNER PRESSURE GAS BRACKET	Damaged	1,092.20 FL	*1,092.20 FL
4	1	*REAR BUMPER LH REFLECTOR	Cracked	39.30 FL	*39.30 FL
5	1	*REAR BUMPER REINFORCEMENT	Dented	536.10 FL	*536.10 FL
6	2	*REAR BUMPER REINFORCEMENT BRACKET L/R	Bent	170.20 FL	*170.20 FL
7	1	*REAR BUMPER REVERSE SENSOR (3 Pcs)	Damaged (2 Pcs only)	1,472.40 FL	*650.00 FL
8	3	*REAR BUMPER REVERSE SENSOR COVER	Necessary	84.00 FL	*84.00 FL
9	3	*REAR BUMPER REVERSE SENSOR HOLDER CLIPS	Necessary	36.30 FL	*36.30 FL
10	2	*REAR BUMPER SIDE RETAINER L/R	Not Necessary	252.20 FL	*- FL
11	1	*REAR END PANEL	Dented	893.90 FL	*893.90 FL
12	1	*REAR END PANEL AIR VENT	Not Necessary	34.80 FL	*- FL
13	1	*REAR END PANEL ANTENNA SENSOR	Cracked	212.10 FL	*212.10 FL
14	1	*REAR END PANEL INNER TOP GARNISH	Deformed	251.30 FL	*251.30 FL
15	1	*REAR LH TAILLAMP	Cracked	674.00 FL	*674.00 FL
16	1	*REAR TAILGATE	Dented	1,806.70 FL	*1,806.70 FL
17	1	*REAR TAILGATE CT200H EMBLEM	Necessary	79.10 FL	*79.10 FL
18	1	*REAR TAILGATE LEXUS EMBLEM	Necessary	68.20 FL	*68.20 FL
19	2	*REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R	Not Necessary	20.00 FL	*- FL
20	1	*REAR TAILGATE INNER TRIM GARNISH	Not Necessary	363.70 FL	*- FL
21	1	*REAR TAILGATE MECHANISM LOCK	Damaged	467.60 FL	*467.60 FL
22	1	*REAR TAILGATE OUTER GARNISH	Cracked	1,104.70 FL	*1,104.70 FL
23	1	*REAR TAILGATE OUTER GARNISH LOGO EMBLEM	Necessary	182.80 FL	*182.80 FL
24	2	*REAR TAILGATE REFLECTOR GASKET SEAL L/R	Not Necessary	78.20 FL	*- FL
25	1	*REAR TAILGATE REFLECTOR L/R	N/s Cracked	944.20 FL	*472.10 FL
26	1	*REAR TAILGATE WEATHER STRIP	Not Necessary	409.30 FL	*- FL
27	1	*REAR TAILGATE WINDSCREEN LOWER MOULDING	Necessary	38.60 FL	*38.60 FL
28	2	*REAR TAILGATE WINDSCREEN MOULDING L/R	Necessary	77.20 FL	*77.20 FL
29	1	*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
30	1	*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
31	1	*SET REAR LH TAILLAMP CLIPS	Necessary	30.00 FS	*10.00 FS
32	1	*REAR TAILGATE INNER RUBBER MOULDING	Necessary	80.00 FS	*20.00 FS
33	1	*SET REAR TAILGATE INNER TRIM GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
34	1	*SET REAR TAILGATE OUTER GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
35	1	*REAR TAILGATE WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>12,877.00</b>	<b>10,056.70</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	1,252.70	989.67
<b>Total Parts (\$\$)</b>	<b>11,624.30</b>	<b>9,067.03</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RESET SYSTEM AFTER REPAIR WORKS	New	250.00	0.00
2	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,AND REWIRE FOR PARKING SENSOR	New	60.00	60.00
3	TO REMOVE,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
4	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR)	New	120.00	80.00
5	TO RE-SPRAY PAINTING ON THE REAR BOOTLID,REAR END PANEL,REAR FENDER (L/R),SPARE TYRE PANEL AND REAR BUMPER	New	1,400.00	800.00
6	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,200.00	800.00
7	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	80.00	60.00
8	TO REMOVE,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,340.00</b>	<b>2,000.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >