

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/III21006697/APA3Q2**Date:** 23/05/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_01

Claimant Vehicle No : SFG825D **Insured Vehicle No :** YQ1363K

Date of Loss: 04/06/2021 Nature of Claim: TP Claim No: MFL2021D0002547

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFG825D**

Make & Model: OPEL ASTRA ST, 999cc (A) Engine No: B1163337GT2X0802

Reg. Date: 14/03/2018 (Man. Year: 2017) Chassis No: W0LBE8EA7H8038220

Colour: Red Odometer: 88895 km

Engine Capacity: 999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,955.20	7,332.80	3,622.40	33.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,170.00	1,060.00	1,110.00	51.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,125.20	8,392.80	4,732.40	36.06
+ GST 7.00/7.00% (S\$)	918.76	587.50	331.26	36.06
Nett Amount (S\$)	14,043.96	8,980.30	5,063.66	36.06
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		9,287.75		
Global Sum Settlement (S\$)		9,280.00		

INSPECTION

Date of Assignment: 14/06/2021

Date Inspected: 14/06/2021 Inspected At: Xin Hua Workshop Pte Ltd (HQ)
23 Kaki Bukit Ave 4 #04-01
Singapore 415933

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Oct 2021)	
Parts:	N/A	OPEL ASTRA ST 999cc (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFG825D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET	Not Necessary	1,318.00 FL	*- FL
2	1		*FRT BUMPER	Torn	1,495.00 FL	*1,495.00 FL
3	1		*FRT BUMPER SIDE RETAINER LH -GUIDE	Cracked	136.00 FL	*136.00 FL
4	1		*FRT BUMPER SIDE RETAINER LH -UPP	Not Necessary	106.00 FL	*- FL
5	1		*FRT BUMPER BRACKET LH	Cracked	192.00 FL	*192.00 FL
6	1		*FRT BUMPER BRACKET TOP CENTRE	Not Necessary	198.00 FL	*- FL
7	1		*FRT BUMPER SPONGE	Cracked	254.00 FL	*254.00 FL
8	1		*FRT BUMPER PARKING SENSOR	Not Necessary	272.00 FL	*- FL
9	1		*FRT BUMPER PARKING SENSOR SEAL	Not Necessary	12.00 FL	*- FL
10	1		*FRT GRILLE ASSY	Cracked	800.00 FL	*800.00 FL
11	1		*FRT GRILLE LOGO	Not Necessary	160.00 FL	*- FL
12	1		*DAYLIGHT CONTROL UNIT	Not Necessary	664.00 FL	*- FL
13	1		*LH HEADLAMP (ILUX)	Cracked	3,235.00 FL	*3,235.00 FL
14	1		*HIGH BEAM CONTROL UNIT	Damaged	792.00 FL	*792.00 FL
15	1		*LOW BEAM CONTROL UNIT	Damaged	1,188.00 FL	*1,188.00 FL
16	1		*LH FOG LAMP	Not Necessary	325.00 FL	*- FL
17	1		*LH FOG LAMP COVER	Not Necessary	120.00 FL	*- FL
18	1		*FRT FENDER LH	Not Necessary	511.00 FL	*- FL
19	1		*FRT NUMBER PLATE WITH COVER	Not Necessary	65.00 FS	*- FS
20	10		*FRT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
21	10		*FRT FENDER INNER SHIELD CLIP	Not Necessary	60.00 FS	*- FS
22	10		*FRT GRILLE CLIP	Necessary	60.00 FS	*20.00 FS
23	1		*BODY PANEL JOINT SEALER	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,133.00	8,142.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,177.80	809.20
Total Parts (\$\$)	10,955.20	7,332.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	600.00	300.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA,FRT BONNET ,FRT BUMPER ,FRT FENDER LH	New	800.00	400.00
3	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	80.00	0.00
4	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	120.00	30.00
5	TO REFOCUS HEADLAMP	New	120.00	20.00
6	TO REMOVE AND REFIX FROTN SENSOR AND CONDUCT TEST	New	100.00	60.00
7	TO PERFORM DIAGNOSSIS RESET ON FAULTY CODE	New	350.00	250.00
Gross Labour Cost (\$\$)			2,170.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >