

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Tel : 6721-9016 Fax : 6844-5185

Reg : 201838521G

Vehicle Number : SFG825D

Date : 09/06/2021

Vehicle Model : OPEL ASTRA

Chassis : W0LBE8EA7H8038220

Accident Date : 04/06/2021

TP Ins. INDIA INT INS

Original Reg Date : 14/3/2018

Xiao Tony.

ESTIMATE

1	FRT BONNET	<i>Not m</i>		\$ 1,318.00
1	FRT BUMPER		<i>torn</i>	\$ 1,495.00
1	FRT BUMPER SIDE RETAINER LH - GUIDE	<i>cracked</i>		\$ 136.00
1	FRT BUMPER SIDE RETAINER LH - UPP	<i>Not m</i>		\$ 106.00
1	FRT BUMPER BRACKET LH	<i>cracked</i>		\$ 192.00
1	FRT BUMPER BRACKET TOP CENTRE	<i>Not m</i>		\$ 198.00
1	FRT BUMPER SPONGE	<i>cracked</i>		\$ 254.00
1	FRT BUMPER PARKING SENSOR	<i>Not m</i>		\$ 272.00
1	FRT BUMPER PARKING SENSOR SEAL	<i>Not m</i>		\$ 12.00
1	FRT GRILLE ASSY	<i>cracked</i>		\$ 800.00
1	FRT GRILLE LOGO	<i>Not m</i>		\$ 160.00
1	DAYLIGHT CONTROL UNIT	<i>Not m</i>		\$ 664.00
1	LH HEADLAMP(ilux)	<i>cracked</i>		\$ 3,235.00
1	HIGH BEAM CONTROL UNIT	<i>Damaged</i>		\$ 792.00
1	LOW BEAM CONTROL UNIT	<i>Damaged</i>		\$ 1,188.00
1	LH FOG LAMP	<i>Not m</i>		\$ 325.00
1	LH FOG LAMP COVER			\$ 120.00
1	FRT FENDER LH	<i>Not m</i>		\$ 511.00

8092

7282.80

\$ 11,778.00
 Less 10% \$ 1,177.80
 \$ 10,600.20

Special Nett

1	1 pc	Frt Number Plate with Cover <i>new</i>	\$ 65.00	+
2	10 pc	Frt Bumper Clip <i>new</i>	\$ 50.00	30
3	10 pc	Frt Fender Inner Shield Clip <i>new</i>	\$ 60.00	+
4	10 pc	Frt Grille clip <i>new</i>	\$ 60.00	20
5	1 pc	Body Panel Joint Sealer <i>new</i>	\$ 120.00	+

50

Labour charge

To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 600.00	300.
Carry out spray painting on accident affected area, FRT BONNET, FRT BUMPER, FRT FENDER LH	\$ 800.00	400
To conduct anti rust of under carriage tuff coat	\$ 80.00	x
To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 120.00	30
To refocus headlamp	\$ 120.00	+ 20
To remove and refix front sensor and conduct test	\$ 100.00	60
To perform diagnosis reset on faulty code	\$ 350.00	150

1060

Total \$ 13,125.20

GST 7% \$ 918.76

Grand Total \$ 14,043.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian G

14/06/21

P/P

03 Days.

total: 8352.80

(P/P)



Trouble codes

VCL 14.07V

DTC history status : History
Since DTC clear : Passed
Last test : Failed current DTC
This ignition cycle : Passed
MIL status : Requested

Lost communication with left
headlamp high beam control module -
Malfunction

U0241-00

VIN:W0LBE8EA7H8038220
Car: Opel/Astra-K

Service
manual

Freeze
frame

Search

Clear
DTC

ESC





Auto scan

VCL 14.03V

100%

List

4 Headlamp control module Fault | 1 ADAS >

5 Transmission control module Pass | No Fault >

6 Electronic brake control module Pass | No Fault >

7 Inflatable restraint sensing and diagnostic module Pass | No Fault >

8 Active safety control module -!- ADAS >

9 Instrument cluster Pass | No Fault >

10 Diagnostic control module Pass | No Fault >

VIN: W0LBE8EA7H8038220
Car: Opel/Astra-K

Report

Quick
erase

OK

Pause

ESC



VCL



97%

21:41