

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III21006699/TGS3Q2**Date:** 14/02/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MCV0003955  
**Claimant Vehicle No :** SJS464B **Insured Vehicle No :** GBG2564R  
 Date of Loss: 10/06/2021 Nature of Claim: TP Claim No: MCV2021D0002489

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJS464B**  
 Make & Model: TOYOTA ALLION, 1.5 (A) Engine No: 1NZD451047  
 Reg. Date: 28/07/2009 (Man. Year: 2009) Chassis No: NZT2603048030  
 Colour: Silver Odometer: 407125 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                            | 16,175.60         | 13,383.55         | 2,792.05          | 17.26         |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour                                           | 5,590.00          | 3,700.00          | 1,890.00          | 33.81         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing                                           | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>              | <b>21,765.60</b>  | <b>17,083.55</b>  | <b>4,682.05</b>   | <b>21.51</b>  |
| <b>Approved Total (Overridden) (S\$)</b>         |                   | <b>13,500.00</b>  |                   |               |
| <b>(S\$)</b>                                     | 21,765.60         | 13,500.00         | 8,265.60          | 37.98         |
| <b>+ GST 7.00/7.00% (S\$)</b>                    | 1,523.59          | 945.00            | 578.59            | 37.98         |
| <b>Nett Amount (S\$)</b>                         | <b>23,289.19</b>  | <b>14,445.00</b>  | <b>8,844.19</b>   | <b>37.98</b>  |
| <b>+ Loss of Use (16.0 x S\$50.00/day) (S\$)</b> |                   | 800.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                    |                   | 36.45             |                   |               |
| <b>+ Other Costs (S\$)</b>                       |                   | 50.00             |                   |               |
| <b>Nett Liability (S\$)</b>                      |                   | <b>15,331.45</b>  |                   |               |
| <b>Global Sum Settlement (S\$)</b>               |                   | <b>15,000.00</b>  |                   |               |

INSPECTION

Date of Assignment: 15/06/2021  
 Date Inspected: 16/06/2021 Inspected At: Em-1 Auto Pte Ltd (HQ)  
 Estimated Period of Repair: 14.0 days Blk 8 Sin Ming Industrial Estate Sector C, #01-68  
 Singapore 575643

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                         |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 13 Oct 2021)           |
| <b>Parts:</b>        | 143                                                                                                                                                                          | TOYOTA ALLION 1.5 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                       |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SJS464B)                                                                                                                                     |                                                         |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                         |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                         |

### Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition                         | Repairer's  | Amount       |
|-----|-----|----------|---------------------------------------|-----------------------------------|-------------|--------------|
| 1   | 1   |          | *BOOT LID                             | Bent                              | 869.20 FL   | *869.20 FL   |
| 2   | 1   |          | *BOOT LID BADGE                       | Necessary                         | 62.20 FL    | *62.20 FL    |
| 3   | 1   |          | *BOOT LID EMBLEM ALLION               | Necessary                         | 63.50 FL    | *63.50 FL    |
| 4   | 1   |          | *BOOT LID EMBLEM A15                  | Necessary                         | 52.00 FL    | *52.00 FL    |
| 5   | 1   |          | *BOOT LID CHROME MOULDING             | Cracked                           | 236.50 FL   | *236.50 FL   |
| 6   | 1   |          | *BOOT LID CHROME MOULDING CLIPS       | Necessary                         | 30.00 FL    | *10.00 FL    |
| 7   | 2   |          | *BOOT LID NUMBER PLATE LAMPS          | Cracked                           | 104.00 FL   | *104.00 FL   |
| 8   | 1   |          | *BOOT LID OPENER SWITCH               | Distorted                         | 198.00 FL   | *198.00 FL   |
| 9   | 4   |          | *BOOT LID STOPPER                     | Not Necessary                     | 72.00 FL    | *- FL        |
| 10  | 1   |          | *BOOT LID INNER LOCK                  | Bent                              | 301.30 FL   | *301.30 FL   |
| 11  | 1   |          | *BOOT LID LOCK CATCH                  | Bent                              | 46.20 FL    | *46.20 FL    |
| 12  | 1   |          | *BOOT LID WEATHERSTRIP                | Torn                              | 189.60 FL   | *189.60 FL   |
| 13  | 1   |          | *BOOT LID UNSULATOR                   | Deformed                          | 321.70 FL   | *321.70 FL   |
| 14  | 1   |          | *SET BOOT LID UNSULATOR CLIPS         | Necessary                         | 30.00 FL    | *10.00 FL    |
| 15  | 1   |          | *BOOT LID HINGES                      | O/S Not Necessary<br>/N/SDeformed | 250.00 FL   | *125.00 FL   |
| 16  | 1   |          | *BOOT LID HINGES COVER                | O/S Not Necessary<br>/N/SDeformed | 184.00 FL   | *92.00 FL    |
| 17  | 1   |          | *REAR BUMPER                          | Deformed                          | 1,126.60 FL | *1,126.60 FL |
| 18  | 2   |          | *REAR BUMPER SIDE RETAINERS           | Necessary                         | 98.00 FL    | *98.00 FL    |
| 19  | 1   |          | *SET REAR BUMPER CLIPS                | Necessary                         | 50.00 FL    | *30.00 FL    |
| 20  | 2   |          | *REAR BUMPER DAMPERS                  | Bent                              | 164.20 FL   | *164.20 FL   |
| 21  | 2   |          | *REAR BUMPER REFLECTORS               | Cracked                           | 158.40 FL   | *158.40 FL   |
| 22  | 1   |          | *END PANEL                            | Bent                              | 672.50 FL   | *672.50 FL   |
| 23  | 1   |          | *END PANEL TOP TRIM                   | Deformed                          | 192.00 FL   | *192.00 FL   |
| 24  | 1   |          | *SET END PANEL TOP TRIM CLIPS         | Necessary                         | 30.00 FL    | *30.00 FL    |
| 25  | 1   |          | *REAR KEY ANTENNA SENSOR              | Cracked                           | 175.60 FL   | *175.60 FL   |
| 26  | 1   |          | *SPARE TYRE PANEL                     | Buckled                           | 975.20 FL   | *975.20 FL   |
| 27  | 1   |          | *SPARE TYRE COMPARTMENT SIDE PANEL LH | Bent                              | 185.30 FL   | *185.30 FL   |
| 28  | 1   |          | *SPARE TYRE PANEL TOP BOARD           | Deformed                          | 191.90 FL   | *191.90 FL   |
| 29  | 1   |          | *SPARE TYRE PANEL TOP SIDE BOARD LH   | Deformed                          | 72.00 FL    | *72.00 FL    |
| 30  | 1   |          | *SPARE TYRE PANEL TOP TOOL SPONGE     | Cracked                           | 93.50 FL    | *93.50 FL    |
| 31  | 1   |          | *SPARE TYRE WHEEL NUT                 | Bent                              | 46.00 FL    | *46.00 FL    |
| 32  | 1   |          | *REAR CHASSIS FRAME MEMBER LH         | Buckled                           | 901.80 FL   | *901.80 FL   |
| 33  | 2   |          | *REAR AIR VENT                        | Deformed                          | 112.00 FL   | *112.00 FL   |
| 34  | 1   |          | *REAR FENDERS                         | O/S Repair / N/S Bent             | 1,946.80 FL | *973.40 FL   |
| 35  | 1   |          | *REAR FENDERS TOP SIDE JOINT PANEL    | O/S Repair / N/S Bent             | 284.00 FL   | *142.00 FL   |
| 36  | 2   |          | *REAR FENDER INNER TRIM               | Torn                              | 659.00 FL   | *659.00 FL   |
| 37  | 2   |          | *REAR FENDER INNER TRIM CLIPS         | Necessary                         | 60.00 FL    | *30.00 FL    |
| 38  | 2   |          | *REAR FENDER INNER SHIELD             | Deformed                          | 113.80 FL   | *113.80 FL   |
| 39  | 2   |          | *SET REAR FENDER INNER SHIELD CLIP    | Necessary                         | 50.00 FL    | *50.00 FL    |
| 40  | 1   |          | *REAR WINDSCREEN                      | Cracked                           | 1,192.00 FL | *1,192.00 FL |
| 41  | 1   |          | *REAR WINDSCREEN MOULDING             | Necessary                         | 131.60 FL   | *131.60 FL   |
| 42  | 1   |          | *REAR WINDSCREEN INNER SEAL           | Necessary                         | 50.00 FL    | *50.00 FL    |
| 43  | 2   |          | *TAILLAMPS                            | Cracked                           | 620.00 FL   | *620.00 FL   |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                                   | Condition             | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------------------------|-----------------------|-------------|--------------|
| 44  | 2   |          | *TAILLAMPS INNER SEALER                       | Not Necessary         | 60.00 FL    | *- FL        |
| 45  | 2   |          | *SET TAILLAMPS CLIPS                          | Necessary             | 50.00 FL    | *50.00 FL    |
| 46  | 1   |          | *TAILLAMP PANEL                               | O/S Repair / N/S Bent | 276.00 FL   | *138.00 FL   |
| 47  | 2   |          | *TAILLAMP BOTTOM RETAINERS                    | Necessary             | 110.00 FL   | *110.00 FL   |
| 48  | 1   |          | *REAR DOOR LH                                 | Repair                | 1,397.00 FL | *- FL        |
| 49  | 1   |          | *REAR DOOR BLACK STICKER LH                   | Necessary             | 75.00 FL    | *75.00 FL    |
| 50  | 1   |          | *REAR DOOR QUARTER GLASS RUBBER LH            | Necessary             | 86.00 FL    | *86.00 FL    |
| 51  | 1   |          | *REAR DOOR INNER LOCK LH                      | Bent                  | 697.40 FL   | *697.40 FL   |
| 52  | 1   |          | *REAR DOOR WEATHERSTRIP LH                    | Necessary             | 287.70 FL   | *287.70 FL   |
| 53  | 1   |          | *REAR WIPER MOTOR                             | Bent                  | 168.30 FL   | *168.30 FL   |
| 54  | 1   |          | *REAR WIPER MOTOR ARM                         | Distorted             | 513.00 FL   | *513.00 FL   |
| 55  | 1   |          | *REAR WIPER MOTOR COVER                       | Distorted             | 18.00 FL    | *18.00 FL    |
| 56  | 1   |          | *REAR WIPER MOTOR BLADE                       | Cut                   | 63.00 FL    | *63.00 FL    |
| 57  | 1   |          | *REAR WIPER MOTOR NOZZLE                      | Distorted             | 45.00 FL    | *45.00 FL    |
| 58  | 1   |          | *REAR WIPER MOTOR BOTTOM RETAINER COVER       | Distorted             | 72.50 FL    | *72.50 FL    |
| 59  | 1   |          | *REAR SPEAKER TOP BOARD                       | Deformed              | 472.00 FL   | *472.00 FL   |
| 60  | 1   |          | *SET REAR SPEAKER TOP BOARD CLIP              | Necessary             | 30.00 FL    | *30.00 FL    |
| 61  | 2   |          | *REAR SPEAKER SIDE BOARD                      | Deformed              | 424.00 FL   | *424.00 FL   |
| 62  | 2   |          | *SETS REAR SPEAKER SIDE BOARD CLIPS           | Necessary             | 40.00 FL    | *40.00 FL    |
| 63  | 1   |          | *FRONT SEAT RH                                | Bent                  | 1,453.50 FL | *1,453.50 FL |
| 64  | 1   |          | *SET BRAKE DOWN SIGN                          | Cracked               | 120.00 FS   | *120.00 FS   |
| 65  | 1   |          | *REAR NUMBER PLATE WITH COVER                 | Bent                  | 70.00 FS    | *45.00 FS    |
| 66  | 1   |          | *REAR WINDSCREEN SEALANT                      | Necessary             | 60.00 FS    | *60.00 FS    |
| 67  | 1   |          | *SET BODY PANEL JOINT SEALANT                 | Necessary             | 120.00 FS   | *50.00 FS    |
| 68  | 1   |          | *REAR FLOOR PANEL INSULATOR PAD               | Necessary             | 150.00 FS   | *100.00 FS   |
| 69  | 1   |          | *SET REVERSE CAMERA                           | Necessary             | 450.00 FS   | *250.00 FS   |
| 70  | 1   |          | *SET REVERSE SENSOR                           | Necessary             | 250.00 FS   | *200.00 FS   |
| 71  | 1   |          | *SET REAR WINDSCREEN GRAB STICKER WITH LABOUR | Necessary             | 100.00 FS   | *40.00 FS    |
| 72  | 1   |          | *SET REAR FENDER GRAB STICKER                 | Necessary             | 80.00 FS    | *60.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                  |
|------------------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$\$)</b>                                    | <b>21,100.80</b> | <b>17,536.40</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | 4,925.20         | 4,152.85         |
| <b>Total Parts (\$\$)</b>                                  | <b>16,175.60</b> | <b>13,383.55</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                            | Particulars                              | Lab.Type | Repairer's      | Amount          |
|-------------------------------|------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>           |                                          |          |                 |                 |
| 1                             | PANEL BEATING                            | New      | 2,200.00        | 1,600.00        |
| 2                             | SPRAY PAINTING                           | New      | 2,000.00        | 1,500.00        |
| 3                             | CHECK WIRING                             | New      | 50.00           | 30.00           |
| 4                             | ANTI RUST                                | New      | 180.00          | 50.00           |
| 5                             | REMOVE AND INSTALL REAR WINDSCREEN       | New      | 140.00          | 120.00          |
| 6                             | REMOVE AND INSTALL CARPET AND SEAT       | New      | 150.00          | 60.00           |
| 7                             | REMOVE AND INSTALL REVERSE SENSOR        | New      | 90.00           | 30.00           |
| 8                             | REMOVE AND INSTALL REVERSE CAMERA        | New      | 150.00          | 30.00           |
| 9                             | REMOVE AND INSTALL PETROL TANK           | New      | 120.00          | 0.00            |
| 10                            | REMOVE AND INSTALL REAR EXHAUST SILENCER | New      | 120.00          | 80.00           |
| 11                            | REMOVE AND INSTALL REAR DOOR PART        | New      | 90.00           | 0.00            |
| 12                            | TO JACK AND ALIGNMENT CHASSIS FRAME      | New      | 300.00          | 200.00          |
| <b>Gross Labour Cost (\$)</b> |                                          |          | <b>5,590.00</b> | <b>3,700.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >