

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21006700/VVF3Q2
Date: 29/06/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Claimant Vehicle No : FBN9209J

Date of Loss: 06/06/2021

Policy No:

Insured Vehicle No :

SJN1361J

Nature of Claim:

TP

Claim No:

8737445634SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBN9209J**

Make & Model: HONDA ACCORD, 1.6 (M)

Reg. Date: 03/01/2019 (Man. Year: 2018)

Colour: Green

Engine Capacity: 150 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: G3E6E0458895

Chassis No: MH3UG0740J0141654

Odometer: 87439 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Handbrake (Serviceable):

Yes

Steering (Serviceable):

Engine Modification:

Yes

No

Footbrake (Serviceable):

Pre-accident Condition:

Yes

CONDITION OF TYRES

Front Tyre Size: 80/90-17

Front Left Side: DIABLO 5 mm

Front Right Side: 0 mm

Rear Tyre Size:

Rear Left Side:

Rear Right Side:

80/90-17

DIABLO 5 mm

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

6/29/2021

Adjuster Report

Date of Assignment: 15/06/2021

Date Inspected: 15/06/2021

Inspected At:

Ong Motor Trading (MACPHERSON RD)
No. 464 Macpherson Road
Singapore 368182

Estimated Period of Repair: 3.0 days

Adjuster: Thevan Thomas Karthikesavan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE:\$8,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT HEADLAMP FAIRING	Cut	0.00 F	*- F
2	1		*HANDLE BAR	Bent	0.00 F	*- F
3	1		*HANDLE BAR GRIP	Cut	0.00 F	*- F
4	1		*HANDLE BAR BALANCER RH	Cut	0.00 F	*- F
5	1		*SIDE FAIRING	*Check	0.00 F	*- F
6	1		*SIDE FAIRING TOP GARNISH	Cut	0.00 F	*- F
7	1		*EXHAUST MUFFLER HEAT SHIELD	Cut	0.00 F	*- F
8	1		*EXHAUST MUFFLER ASSY	Cut	0.00 F	*- F
9	1		*REAR SPOCKET	*Check	0.00 F	*- F
10	1		*REAR SUB FRAME	*Check	0.00 F	*- F
11	1		*REAR TAILLAMP	Cracked	0.00 F	*- F
12	1		*REAR NUMBER PLATE	Bent	0.00 F	*- F
13	1		*REAR MUDGUARD	Distorted	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)
0.00
0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >