

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21006708/R1TCE2

Date: 18/10/2021

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No: DMCVSNW00078922001

Claimant Vehicle No : YP8862X

Insured Vehicle No : GBF4800B

Date of Loss: 07/06/2021

Nature of Claim: TP

Claim No: SNM21D203247/C02/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YP8862X**

Make & Model: ISUZU NPR85UH5A, 3.0 D (M)

Engine No: 4JJ13M5370

Reg. Date: 12/06/2018 (Man. Year: 2018)

Chassis No: JAANPR85HJ7100107

Colour: White

Odometer: 85141 km

Engine Capacity: 2999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/85 R16

Rear Tyre Size: 195/85 R16

Front Left Side: Bridgestone 7 mm

Rear Left Side: Bridgestone 7/7 mm

Front Right Side: Bridgestone 7 mm

Rear Right Side: Bridgestone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,600.00	3,060.00	540.00	15.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,141.00	1,950.00	1,191.00	37.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,741.00	5,010.00	1,731.00	25.68
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	6,741.00	4,000.00	2,741.00	40.66
+ GST 7.00/7.00% (S\$)	471.87	280.00	191.87	40.66
Nett Amount (S\$)	7,212.87	4,280.00	2,932.87	40.66

INSPECTION

Date of Assignment: 15/06/2021

Date Inspected: 16/06/2021 Inspected At:

Central Automotive Pte Ltd (HQ)
1 Sunview Road, #08-44 Eco-Tech@Sunview
Singapore 627615

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT BUT NOT AGREED WITH OUR RECOMMENDATION.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Oct 2021)	
Parts:	N/A	ISUZU NPR85UH5A 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP8862X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET FRONT BUMPER	Deformed	1,200.00 F	*1,200.00 FL
2	1		*SET LEFT FRAME GUARD	Bent	530.00 F	*530.00 FL
3	1		*LOT LEFT LIGHT ASSEMBLY AND BRACKET	Broken	780.00 F	*780.00 FL
4	1		*LOT LEFT CORING ENCLOSE	Missing	680.00 F	*680.00 FL
5	1		*LEFT SIDE MIRROR AND HOLDER ASSEMBLY	Missing	410.00 F	*410.00 FL
					Sub Total (\$)	3,600.00
					- List Item Discount on L Items 0.00/15.00% (\$)	0.00
					Total Parts (\$)	3,600.00

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEATING AND REPAIR OF CABIN LEFT FRAME	New	450.00	250.00
2	TO REPAIR LEFT DOOR AND REALIGNMENT	New	511.00	200.00
3	TO RESPRAY CABIN	New	900.00	800.00
4	TO REPLACE CABIN ARTWORK	New	380.00	200.00
5	TO REMOVE AND INSTALL BODY PARTS	New	900.00	500.00
			Gross Labour Cost (\$)	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >