

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21006710/EUCE2

Date: 24/09/2021

REFERENCE

Insured/Claimant: KOH BOON HOU ALVIN Policy No: DMPCNA00026022100

Date of Loss: 02/06/2021

Nature of Claim: OD

Claim No: SNM21D203178/C01/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMQ9431L**

Make & Model: AUDI A1 SPORTBACK, 1.0 TFSI S-tronic (A)

Engine No: DKJ043809

Reg. Date: 11/12/2019 (Man. Year: 2019)

Chassis No: WAUZZZGB1LR006217

Colour: Yellow

Odometer: 37148 km

Engine Capacity: 999 cc

Market Value/New Car Price: S\$125,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Rear Tyre Size: 215/45 R17

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|------------------|------------------|------------------|--------------|
| Parts | 39,644.10 | 29,759.20 | 9,884.90 | 24.93 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 17,792.00 | 13,242.00 | 4,550.00 | 25.57 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 57,436.10 | 43,001.20 | 14,434.90 | 25.13 |
| + GST 7.00/7.00% (S\$) | 4,020.53 | 3,010.08 | 1,010.45 | 25.13 |
| Nett Amount (S\$) | 61,456.63 | 46,011.28 | 15,445.35 | 25.13 |

INSPECTION

Date of Assignment: 15/06/2021

Date Inspected: 16/06/2021 Inspected At:

24 Benoi Sector

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair: 18.0 days

Adjuster: CHEN TSUE YEE

Manager: Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 24 Sep 2021) |
| Parts: | 144 | AUDI A1 SPORTBACK 1.0 TFSI S-tronic (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SMQ9431L) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. Particulars | Condition | Repairer's | Amount |
|-----|-----|----------------------------------------------------|---------------|-------------|--------------|
| 1 | 1 | *FRONT BUMPER | Broken | 1,634.00 FS | *1,634.00 FS |
| 2 | 1 | *FRONT BUMPER FIXING PARTS | Not Necessary | 137.00 FS | *- FS |
| 3 | 2 | *FRONT BUMPER SPOILER LH / RH | Not Necessary | 200.00 FS | *- FS |
| 4 | 1 | *FRONT BUMPER AIR GUIDE GRILLE - LH / RH | O/S Broken | 422.00 FS | *210.50 FS |
| 5 | 1 | *FRONT BUMPER GRILLER - CENTER | Not Necessary | 196.00 FS | *- FS |
| 6 | 1 | *FRONT BUMPER CLOSING ELEMENT | Not Necessary | 167.00 FS | *- FS |
| 7 | 1 | *RADIATOR GRILLE | Broken | 926.00 FS | *926.00 FS |
| 8 | 1 | *FRONT BUMPER TOP MOUNT BRACKET | Cracked | 161.00 FS | *160.50 FS |
| 9 | 1 | *FRONT BUMPER REINFORCEMENT BEAM | Bent | 723.00 FS | *723.00 FS |
| 10 | 1 | *FRONT FOAM FILLER PIECE | Broken | 118.00 FS | *117.50 FS |
| 11 | 1 | *FRONT BUMPER TOP COVER | Broken | 123.00 FS | *122.50 FS |
| 12 | 2 | *FRONT BUMPER GUIDE SECTION - LH / RH | Cracked | 214.00 FS | *214.00 FS |
| 13 | 1 | *FRONT BUMPER GUIDE PROFILE LH / RH | O/S Cracked | 72.00 FS | *35.40 FS |
| 14 | 1 | *CAUTION SIGN STICKER | Necessary | 14.00 FS | *13.60 FS |
| 15 | 1 | *AC STICKER | Necessary | 19.00 FS | *18.50 FS |
| 16 | 1 | *HORN LH | Not Necessary | 137.00 FS | *- FS |
| 17 | 1 | *HORN RH | Not Necessary | 130.00 FS | *- FS |
| 18 | 1 | *HORN BRACKET LH | Not Necessary | 41.00 FS | *- FS |
| 19 | 2 | *HORN BRACKET RH | Not Necessary | 31.00 FS | *- FS |
| 20 | 2 | *FRONT FENDER LH / RH | Dented | 1,956.00 FS | *1,956.00 FS |
| 21 | 2 | *FRONT FENDER BRACKET - LH / RH | Bent | 72.60 FS | *72.60 FS |
| 22 | 2 | *FRONT FENDER BRACKET - LH / RH | Not Necessary | 28.00 FS | *- FS |
| 23 | 2 | *FRONT FENDER BRACKET - LH / RH | Not Necessary | 116.00 FS | *- FS |
| 24 | 2 | *FRONT FENDER BRACE LH / RH | Bent | 108.00 FS | *106.80 FS |
| 25 | 1 | *BONNET | Dented | 2,282.00 FS | *2,282.00 FS |
| 26 | 2 | *BONNET HINGE LH / RH | Bent | 124.00 FS | *122.20 FS |
| 27 | 2 | *BONNET STRIKER LH / RH | Bent | 198.00 FS | *197.80 FS |
| 28 | 1 | *BONNET ATTACHMENT PART (NPA) | Not Necessary | 0.00 FS | *- FS |
| 29 | 2 | *BONNET IMPACT PROTECTION LH / RH | Necessary | 62.00 FS | *60.60 FS |
| 30 | 1 | *BONNET IMPACT PROTECTION CENTER | Necessary | 31.00 FS | *30.30 FS |
| 31 | 1 | *BONNET SOUND ABSORBER | Crushed | 219.00 FS | *219.00 FS |
| 32 | 1 | *BONNET GASKET | Necessary | 93.00 FS | *92.80 FS |
| 33 | 1 | *BONNET BOWDEN CABLE CENTER | Not Necessary | 84.00 FS | *- FS |
| 34 | 2 | *BONNET BOWDEN CABLE LH / RH | Not Necessary | 58.00 FS | *- FS |
| 35 | 2 | *BONNET LOCK WITH MICRO - SWITCH LH / RH | Not Necessary | 427.00 FS | *- FS |
| 36 | 2 | *BONNET LOCK WITH MICRO - SWITCH CONNECTOR LH / RH | Not Necessary | 26.00 FS | *- FS |
| 37 | 1 | *BONNET RELEASE LEVER | Not Necessary | 14.00 FS | *- FS |
| 38 | 1 | *BONNET RELEASE CABLE COVER | Not Necessary | 10.00 FS | *- FS |
| 39 | 1 | *BONNET RELEASE CABLE | Not Necessary | 47.00 FS | *- FS |
| 40 | 1 | *PLENUM CHAMBER COVER (NPA) | Not Necessary | 0.00 FS | *- FS |
| 41 | 2 | *LED HEADLIGHT LH / RH | Broken | 8,576.00 FS | *8,576.00 FS |
| 42 | 2 | *LED HEAT SINK LH / RH | Not Necessary | 1,432.00 FS | *- FS |
| 43 | 2 | *LED HEADLIGHT POWER MODULE LH / RH | Not Necessary | 1,516.00 FS | *- FS |
| 44 | 2 | *LED HEADLIGHT BREATHING HOSE LH / RH | Not Necessary | 60.00 FS | *- FS |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. Particulars | Condition | Repairer's | Amount |
|-----|-----|---------------------------------------------|------------------|-------------|--------------|
| 45 | 2 | *LED HEADLIGHT LIFT CYLINDER LH / RH | Not Necessary | 284.00 FS | *- FS |
| 46 | 1 | *LIFT CYLINDER HOSE | Not Necessary | 59.00 FS | *- FS |
| 47 | 1 | *WINDSCREEN WASHER PUMP | Not Necessary | 125.00 FS | *- FS |
| 48 | 1 | *WASH WATER RESERVOIR | Crushed | 189.00 FS | *189.00 FS |
| 49 | 1 | *WASH WATER RESERVOIR NECK | Not Necessary | 58.00 FS | *- FS |
| 50 | 1 | *LOCK CARRIER | Dented | 1,272.00 FS | *1,272.00 FS |
| 51 | 2 | *LOCK CARRIER BRACE LH / RH UPPER | Dented | 152.00 FS | *151.00 FS |
| 52 | 1 | *A/C CONDENSOR | Dented | 503.00 FS | *503.00 FS |
| 53 | 1 | *A/C REFRIGERANT LINE | Cut | 340.00 FS | *339.50 FS |
| 54 | 1 | *A/C REFRIGERANT HOSE | Not Necessary | 261.00 FS | *- FS |
| 55 | 1 | *OUTSIDE TEMPERATURE SENSOR | Not Necessary | 59.00 FS | *- FS |
| 56 | 1 | *ADDITIONAL RADIATOR | Dented | 931.00 FS | *930.50 FS |
| 57 | 1 | *RADIATOR | Dented | 931.00 FS | *930.50 FS |
| 58 | 2 | *RADIATOR AIR GUIDE LH / RH | Broken | 76.00 FS | *74.40 FS |
| 59 | 2 | *RADIATOR SEALING STRIP LH / RH | Cracked | 62.00 FS | *60.40 FS |
| 60 | 2 | *RADIATOR RUBBER BUSH LH / RH UPPER | Damaged | 82.00 FS | *81.60 FS |
| 61 | 2 | *RADIATOR RUBBER BUSH LH / RH LOWER | Not Necessary | 19.00 FS | *- FS |
| 62 | 6 | *RADIATOR COOLANT | Necessary | 269.00 FS | *268.20 FS |
| 63 | 2 | *RADIATOR FAN | Broken | 1,199.00 FS | *1,199.00 FS |
| 64 | 1 | *AIR INTAKE AIR GUIDE | Broken | 53.00 FS | *52.30 FS |
| 65 | 1 | *AIR INTAKE AIR GUIDE | Broken | 42.00 FS | *41.20 FS |
| 66 | 1 | *INTAKE MANIFOLD PIPE | Not Necessary | 139.00 FS | *- FS |
| 67 | 1 | *AIR FILTER | Not Necessary | 2,745.00 FS | *- FS |
| 68 | 1 | *WATER DRAINAGE HOSE | Not Necessary | 33.00 FS | *- FS |
| 69 | 1 | *INTAKE MANIFOLD | Damaged / Broken | 666.50 FS | *666.50 FS |
| 70 | 1 | *INTAKE MANIFOLD SEAL | Not Necessary | 14.00 FS | *- FS |
| 71 | 1 | *INTAKE THROTTLE VALVE | Not Necessary | 754.00 FS | *- FS |
| 72 | 1 | *INTAKE THROTTLE VALVE SEAL | Not Necessary | 14.00 FS | *- FS |
| 73 | 1 | *INTAKE THROTTLE VALVE O-RING | Not Necessary | 18.00 FS | *- FS |
| 74 | 1 | *RETAINING BAR | Not Necessary | 15.00 FS | *- FS |
| 75 | 2 | *FRONT WHEEL HOUSING LINER LH / RH (NPA) | Not Necessary | 0.00 FS | *- FS |
| 76 | 2 | *FRONT WHEEL HOUSING LINER ATTACHMENT PARTS | Not Necessary | 69.00 FS | *- FS |
| 77 | 1 | *FRONT NO PLATE WITH HOLDER | Broken | 100.00 FS | *100.00 FS |
| 78 | 1 | *SUNDRIES | Necessary | 300.00 FS | *214.30 FS |
| 79 | 1 | *FLAP SUPPORT | Bent | 77.00 FS | *76.20 FS |
| 80 | 1 | *COOLANT HOSE WITH QUICK RELEASE COUPLING | Cracked | 185.00 FS | *185.00 FS |
| 81 | 1 | *COOLANT PIPE | Dented | 30.00 FS | *29.60 FS |
| 82 | 1 | *WIRE | Snapped | 63.00 FS | *62.70 FS |
| 83 | 1 | *WIRE BUTT CONNECTOR | Necessary | 21.00 FS | *20.40 FS |
| 84 | 1 | *BATTERY CONSOLE | Cracked | 129.00 FS | *129.00 FS |
| 85 | 1 | *GEARBOX MECHATRONIC UNIT | Dented | 3,977.00 FS | *3,977.00 FS |
| 86 | 1 | *ATF OIL | Necessary | 186.00 FS | *185.70 FS |
| 87 | 1 | *GEARBOX MECHATRONIC UNIT BOLTS | Necessary | 62.00 FS | *52.80 FS |
| 88 | 1 | *COOLANT HOSE | Cut | 76.00 FS | *75.80 FS |

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 39,644.10 29,759.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------------|------------------|
| Labour Items | | | | |
| 1 | TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR. HEADLIGHT WASHER ASSY | New | 360.00 | 360.00 |
| 2 | TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE | New | 700.00 | 700.00 |
| 3 | TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS | New | 1,200.00 | 1,200.00 |
| 4 | TO RENEW AIR INTAKE MANIFOLD AND OTHER ENGINE COMPONENTS | New | 980.00 | 980.00 |
| 5 | TO DISMANTLE AND RENEW FRONT BUMPER, BONNET BOTH FRONT FENDER AND BOTH HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITON. TO REPAIR BOTH FRONT FENDER TOP SUPPORTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL REMOVED PARTS | New | 6,300.00 | 4,900.00 |
| 6 | TO RESPRAY FRONT BUMPER, BOTH FRONT FENDER, HINGES, BOTH FRONT FENDER TOP SUPPORTS, BOTH AN BOTH FRONT DOOR | New | 6,800.00 | 3,650.00 |
| 7 | TO REMOVE AND REINSTALL FRONT BUMPER LOWER SPOILER | New | 280.00 | 280.00 |
| 8 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 192.00 |
| 9 | TO DISMANTLE AND RENEW GEARBOX MECHATRONIC | New | 980.00 | 980.00 |
| Gross Labour Cost (\$\$) | | | 17,792.00 | 13,242.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >