Adjuster Report 12/2/22, 11:06 AM

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21006711/TQY3E2

02/12/2022 Date:

**REFERENCE** 

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001437475 **Claimant Vehicle** FBQ5515K Insured Vehicle No: SMM7879M

No:

03/06/2021 Nature of Claim: TP Claim No: 258313 Date of Loss:

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: FBQ5515K

Make & Model: YAMAHA SNIPER T150, 150cc Engine No: G3E6E0510096

Reg. Date: 23/10/2019 (Man. Year: 2019) Chassis No: MH3UG0740K0153242

Colour: Dark Green Odometer: 0 km

**Engine Capacity:** 150 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

**CONDITION OF TYRES** 

Front Tyre Size: 70/90 R17 Rear Tyre Size: 120/70 R17 Front Left Side: Rear Left Side: Dunlop 5 mm Dunlop 5 mm Rear Right Side: Front Right Side: 0 mm 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	423.00	358.20	64.80	15.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	680.00	400.00	280.00	41.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,103.00	758.20	344.80	31.26

**INSPECTION** 

Date of Assignment: 15/06/2021

United Cycles Llp (hq) (HQ) Date Inspected: 16/06/2021 Inspected At:

25Kaki Bukit Road 4 #01-25 Synergy @ KB

Singapore 417800

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID SHIAU CHAN Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT BUT NOT AGREED WITH OUR RECOMMENDATION.

## **REPAIR DETAILS**

Reference

Part Source: (Last Synchronised: 01 Dec 2022)

Parts: N/A YAMAHA SNIPER T150 150cc (Model not available in database)

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for FBQ5515K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cut	50.00 F	*50.00 FL
2	1		*HANDLE BALANCER	Missing	15.00 F	*15.00 FL
3	1		*BRAKE LEVER	Cut	18.00 F	*18.00 FL
4	1		*SETS MIRROR	Cut	30.00 F	*30.00 FL
5	1		*SIDE BODY COVER (L/H)	Cut	80.00 F	*80.00 FL
6	1		*SIDE INNER COVER (L/H)	Cut	25.00 F	*25.00 FL
7	1		*FRONT CENTER COWLING	Cut	60.00 F	*60.00 FL
8	1		*FRONT CENTER COVER (INNER)	Deformed	50.00 F	*50.00 FL
9	1		*EXHAUST PROTECTOR COVER	Cut	45.00 F	*45.00 FL
10	1		*EXHAUST COVER (END)	Cut	25.00 F	*25.00 FL
11	1		*BASKET (CENTER)	Not Necessary	25.00 F	*- FL
F=Fr	anchise	e part. L=ListIter	nDisc.			
				Sub Total (S\$)	423.00	398.00
			- List Item Discou	0.00	39.80	
				Total Parts (S\$)	423.00	358.20
				_		

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

12/2/22, 11:06 AM

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	FRONT FORK ALIGNMENTS	New	200.00	120.00
2	LABOUR CHARGES	New	400.00	200.00
3	TOWING X 2 WAYS	New	80.00	80.00
		Gross Labour Cost (S\$)	680.00	400.00
	Repor	t was unsubmitted during this print-out.		

< END OF ESTIMATES >