Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte.

Ltd.

4 Shenton Way

#21-01 SGX Centre 2

Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Jowyn Tay Mei Ling Date: 03 Feb 2022

Preliminary Advice

Insured : SMM7879M

Vehicle No

TP Vehicle : FBQ5515K Accident Date

: 03/06/2021

No

: YAMAHA SNIPER T150

Assignment Date: 15/06/2021

Date of

Make

: 16/06/2021

Est. Duration of

: 6

Inspection

Repair Inspection At: UNITED CYCLES LLP (HQ) (HQ)

25KAKI BUKIT ROAD 4 #01-25 SYNERGY @ KB

SINGAPORE 417800

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 1,103.00 **Revised Amount** :S\$ 758.20 Check Items (Estimated) :S\$ 0.00 Total :S\$ 758.20

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$

Salvage Value	:S\$
Margin for Repair	:S\$

consistency check, part prices and labour cost.

Rema	arks
------	------

()	The vehicle is economical for repair
()	The vehicle is not economical for repair
()	Part-by-Part repair
()	Lump Sum repair
(X)	The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to