LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG21006712/T1VF3E2

Date: 02/09/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900079880

Claimant Vehicle Opening Communication of the Communicati

No: SBS3280P Insured Vehicle No: EZ9933C

Date of Loss: 12/06/2021 Nature of Claim: TP Claim No: 0770209061SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SBS3280P

Make & Model: VOLVO B9TL, 9.4 D (A) Engine No: D9190049

Reg. Date: 25/04/2013 (Man. Year: 2013) Chassis No: YV3S4P926DA160721

Colour: Multi-colour Odometer: 457190 km

Engine Capacity: 9364 cc
Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 8/8 mm
Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,218.85	1,218.85	0.00	0.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		980.00	980.00	0.00	0.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Gross Total	I (S\$)	2,198.85	2,198.85	0.00	0.00
+ GST 7.00/7.00%	s (S\$)	153.92	153.92	0.00	0.00
Nett Amount	t (S\$)	2,352.77	2,352.77	0.00	0.00

INSPECTION

Date of Assignment: 15/06/2021

Sbs Transit Ltd (Bedok) (HQ)
Date Inspected: 17/06/2021 Inspected At: 1470 BEDOK NORTH AVE 4

14/0 DEDUK NORTH AVE 4

Singapore 489946

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*DOOR PILLAR CAPPING;ENT / EXIT DOOR	Cut	79.00 F	*79.00 F	
2	1		*SIDE SHEETMETAL PANEL	Bent	769.00 F	*769.00 F	
3	1		*PILLAR TRIM INFILL	Cut	158.00 F	*158.00 F	
4	2		*GLASS.PANEL 1519X482.LH/RH.EXIT DRO/N/S	Cut	208.00 F	*208.00 F	
5 E=Ers	5 anchise	nart	*WHEEL RESTRAINER & INDICATOR 33MM.PURPLE	Deformed	4.85 F	*4.85 F	
1 -1 16	aricinsc	part.		Total Parts (S\$)	1,218.85	1,218.85	
Report was unsubmitted during this print-out.							

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>			
1 CONTRACTOR LABOUR	New	980.00	980.00
	Gross Labour Cost (S\$)	980.00	980.00
Report v	vas unsubmitted during this print-out.		

< END OF ESTIMATES >