



Accident Reference & Bus No: E/2640/2021 - SBS3280P

Activated date: Tue 6/15/2021 3:13 PM

Activated by: Yao Tianhao <yaoth@sbstransit.com.sg>

Estimate for

Stock Code	Description	Quantity	Total Material cost(S\$)
30750139	DOOR PILLAR CAPPING; ENT/EXIT DOOR	1	\$79.00
30750361	SIDE SHEETMETAL PANEL	1	\$769.00
30750426	PILLAR TRIM INFILL	1	\$158.00
30103423	GLASS.PANEL 1519X482.LH/RH.EXIT DRO/N/S	2	\$208.00
WS33YLNK	WHEEL RESTRAINER & INDICATOR 33MM.PURPLE	5	\$4.85

ext ✓
bt ✓
int ✓
ext ✓
de ✓

- ☐ Parts cost: \$ 1218.85 ✓
- ☐ Contractor Labour cost: \$ 980 +gst ✓
- ☐ Workshop Labour cost: not required by LKK surveyor Xnn
- ☐ Advertisement Cost: \$ 0 Xnn
- ☐ Repair period: 3 days

- ☐ Tow Cost: \$ 0 Xnn
- ☐ Loss of use: not required by LKK surveyor Xnn
- ☐ Overheads: \$ 714.86 Xnn

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3 days #