

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006719/BGA3Q2**Date:** 31/05/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210044135
Claimant Vehicle No :	SKU8783E	Insured Vehicle No :	SKA2629M
Date of Loss:	10/06/2021	Nature of Claim:	TP
		Claim No:	5676576722SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU8783E	Engine No:	K9KN837D197519
Make & Model:	RENAULT FLUENCE, 1.5 D DCI 110 (A)	Chassis No:	VF1LZLF0E53194164
Reg. Date:	20/08/2015 (Man. Year: 2015)	Odometer:	0 km
Colour:	Red		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,226.00	7,065.10	3,160.90	30.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,860.00	2,060.00	1,800.00	46.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,086.00	9,125.10	4,960.90	35.22
Approved Total (Overridden) (S\$)		7,300.00		
(S\$)	14,086.00	7,300.00	6,786.00	48.18
+ GST 7.00/7.00% (S\$)	986.02	511.00	475.02	48.18
Nett Amount (S\$)	15,072.02	7,811.00	7,261.02	48.18
+ Car Rental (11.0 x S\$100.00/day + 7.00% GST) (S\$)		1,177.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,990.00		

INSPECTION

Date of Assignment:	15/06/2021	Chew Goon Motor (AMK)
Date Inspected:	16/06/2021 Inspected At:	Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint
Estimated Period of Repair:	8.0 days	Singapore 568047

Adjuster: Lim Teow Guan**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT	Dented	1,500.00 FL	*1,500.00 FL
2	1		*BOOT EMBLEM	Necessary	110.00 FL	*97.00 FL
3	1		*BOOT LOCK	Jammed	320.00 FL	*267.00 FL
4	1		*BOOT WEATHERSTRIP	Torn	365.00 FL	*209.00 FL
5	1		*BOOT TRIM BOARD	Torn	420.00 FL	*360.00 FL
6	1		*BOOT TRIM BOARD CLIPS (11 PCS)	Necessary	88.00 FL	*30.00 FL
7	1		*BOOT LAMP RH	Broken	330.00 FL	*270.00 FL
8	1		*BOOT LAMP GASKET RH	Necessary	35.00 FL	*35.00 FL
9	1		*REAR BUMPER	Broken	1,350.00 FL	*1,020.00 FL
10	1		*REAR BUMPER CLIPS (11 PCS)	Necessary	70.00 FL	*30.00 FL
11	2		*REAR BUMPER BRACKETS	Broken	290.00 FL	*130.00 FL
12	1		*REAR BUMPER SPONGE	No such part	230.00 FL	*- FL
13	1		*REAR BUMPER REINFORCEMENT	Broken	580.00 FL	*580.00 FL
14	1		*REAR BUMPER CORE	No such part	365.00 FL	*- FL
15	1		*REAR BUMPER SIDE CORE	Broken	195.00 FL	*95.00 FL
16	2		*REAR BUMPER SENSORS	Scratched	568.00 FL	*200.00 FL
17	4		*REAR BUMPER SENSOR HOLDERS	Necessary	140.00 FL	*140.00 FL
18	1		*REAR BUMPER SENSOR WIRING HARNESS	Scratched	350.00 FL	*200.00 FL
19	1		*REAR BUMPER REFLECTOR RH	Not Damaged	150.00 FL	*- FL
20	2		*REAR BUMPER TOP RETAINERS	No such part	244.00 FL	*- FL
21	1		*REAR BUMPER CORNER RETAINER RH	No such part	115.00 FL	*- FL
22	1		*REAR BUMPER INNER BOOT SENSOR	Broken	260.00 FL	*200.00 FL
23	1		*REAR BUMPER TOP BEAM	No such part	360.00 FL	*- FL
24	5		*REAR BUMPER TOP BEAM RIVETS	Necessary	72.50 FL	*72.50 FL
25	1		*TAILLAMP RH	Broken	410.00 FL	*280.00 FL
26	1		*TAILLAMP GASKET	No such part	30.00 FL	*- FL
27	1		*TAILLAMP SIDE GARNISH COVER RH	Broken	160.00 FL	*160.00 FL
28	1		*END PANEL	Dented	720.00 FL	*487.00 FL
29	1		*END PANEL GARNISH	Broken	320.00 FL	*225.00 FL
30	1		*REAR STYROFOAM STORAGE TRAY	Broken	460.00 FL	*310.00 FL
31	1		*REAR FENDER TRIM BOARD	Torn	535.00 FL	*465.00 FL
32	1		*SPARE TYRE TOP BOARD	Dented	490.00 FL	*390.00 FL
33	1		*SPARE TYRE PANEL	Dented	1,150.00 FL	*1,078.88 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	12,782.50	8,831.38
- List Item Discount on L Items 20.00/20.00% (\$)	2,556.50	1,766.28
Total Parts (\$)	10,226.00	7,065.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / TRANSFER BOOT FITTINGS /ANCILLARY ACCESSORIES	New	120.00	80.00
2	TO CONDUCT ELECTRICAL CHECK,REPLACE REVERSE SENSORS ,WIRING HARNESS & REPROGRAM SYSTEM	New	120.00	60.00
3	TO DISMANTLE /REFIT TRUNK COMPARTMENT BOARDS TRIMS	New	120.00	0.00
4	TO SUPPLY REAR PANEL BODY SEALANT	New	100.00	40.00
5	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL	New	150.00	80.00
6	LABOUR CARGE- PANEL BEATING ,REPAIRING OF BOOT HINGE ,REAR CHASSIS MEMBER ,FLOOR PANEL ,REAR O/S FENDER ETC .CNT ,WELD END PANEL SPARE TYRE PANEL AND PARTS REPLACEMENT	New	1,600.00	1,000.00
7	TO RESPRAY AFFECTED AREAS (BOOT ,REAR BUMPER ,END PANEL,SPARE TYRE PANEL,TAILLAMP PANEL,REAR FENDER RH)	New	1,650.00	800.00
Gross Labour Cost (\$\$)			3,860.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >