



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 6209L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT WIPER PANEL	TO REPAIR SEE LABOUR	481.95	-
1	FRONT CAB PANEL	DENTED / BUCKLED	1,378.70	1,378.70
1	FRONT CAB PANEL MOULDING-CTR	MOUNTING BROKEN	291.33	291.33
2	FRONT CAB PANEL MOULDING @\$199.75	MOUNTING BROKEN	399.50	399.50
1	FRONT GRILLE ASSY	BROKEN	587.65	587.65
1	FRONT GRILLE EMBLEM "LOGO"	NECESSARY	86.90	86.90
2	FRONT HEADLAMP @\$892.10	SERVICEABLE	1,784.20	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	561.90	-
	LESS 25% DISCOUNT		-1,393.03	-686.02
			4,179.10	2,058.06
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT GRILLE CLIP (SN)	NECESSARY	24.00	24.00
			24.00	24.00
	<u>LABOUR</u>			
	TO CHECK FRONT ELECTRICAL WIRING & REFOCUS HEADLAMP.	NOT NECESSARY	40.00	-
	TO RESPRAY UNDERCOATING.		100.00	40.00
	TO REMOVE,REFIX A/C COOLING SYSTEM & REFILL GAS.	NOT NECESSARY	150.00	-
	TO RESPRAY PAINTING & ETC.		1,000.00	500.00
	PANEL BEATING,CUT,WELD,REMOVE & REPLACING ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT WIPER PANEL AND FRONT BUMPER.		1,000.00	500.00
			2,290.00	1,040.00
	GRAND TOTAL		6,493.10	3,122.06



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,500.00
---	--	--	-----------------

Report Ref No. CS3/GAI21006115/R1vf3e2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.