

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

INVOICE

To: T.O.P Design & Engineering Pte Ltd
c/o Blk 3, Pioneer Road North
#01-24
Singapore 628457

Date : 04/06/2021

Invoice No : IV21-06001/CAS

Particulars	Amount
Fee For Services Rendered In Respect Of: Surveying, Adjusting, and Re-inspection Of Accident Damaged Vehicle GBC 6209L (Inclusive Of Photographs And Transport Charges) Our reference : CAS/21-06/001	\$582.00
Total	\$582.00

E. & O.E

Constant Appraiser Services



Cheque Should Be Crossed And Made Payment To 'Constant Appraiser Services'

Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: T.O.P Design & Engineering Pte Ltd
c/o Blk 3, Pioneer Road North
#01-24
Singapore 628457

Date : 04/06/2021

Reference No : CAS/21-06/001

General Information

Registration No. : GBC 6209L
Accident Date : 20/05/2021

Particulars of Damaged Vehicle

Colour	: Silver	Make & Model	: Toyota Dyna 150 Manual
Engine Capacity	: 2982 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 553058	Engine No.	: 1KD2281746
Chassis No.	: JTFAT35Y70K202275	Steering	: In Order
Registration Date	: 18/04/2013	Brake	: In Order

Tyre Condition

	Size	Make	Balance
R/H Front Tyre	195R15	FALKEN	80%
L/H Front Tyre	195R15	FALKEN	80%
R/H Rear Tyre	155R12 (D)	DELIUM	60% / 60%
L/H Rear Tyre	155R12 (D)	DELIUM	60% / 60%

Inspection

Repairer : Carport Auto Service
Blk 3, Pioneer Road North, #01-24, Singapore 628457

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$6,493.10
Revised Amount : \$4,100.00
Less Excess : -
Nett Total : \$4,100.00

Remarks

- (A) Survey was done on 27/05/2021
- (B) Re-survey was done on 27/05/2021
- (C) Re-survey after repair was done on 31/05/2021
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT – LIST ITEMS</u>			
1	1pc	Front wiper panel	Repair	481.95	-
2	1pc	Front cab panel	Dented/Buckled	1,378.70	1,378.70
3	1pc	Front cab panel moulding – ctr	Mounting Broken	291.33	291.33
4	2pcs	Front cab panel moulding @ \$199.75	Mounting Broken	399.50	399.50
5	1pc	Front grille assy	Broken	587.65	587.65
6	1pc	Front grille emblem 'logo'	Necessary	86.90	86.90
7	2pcs	Front headlamp @ \$892.10	Broken	1,784.20	1,784.20
8	1pc	Front bumper	Repair	561.90	-
				5,572.13	4,528.28
		Less 25%		(1,393.03)	(1,132.07)
			Sub total	4,179.10	3,396.21
		<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>			
1	1set	Front grille clip	Necessary	24.00	24.00
			Sub total	4,203.10	3,420.21
		<u>LABOUR & MISC. CHARGES</u>			
1		To check front electrical wiring & refocus headlamp		40.00	20.00
2		To respray undercoating		100.00	60.00
3		To remove, refix A/C cooling system & refill gas		150.00	120.00
4		To respray painting & etc		1,000.00	750.00
5		Panel beating, cut, weld, remove & replacing above parts		1,000.00	750.00
			Grand total	6,493.10	5,120.21
Recommended cost of lump sum repair (To its pre-accident condition)					4,100.00

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$4,100.00** on a contractual basis. Under normal circumstances, the repair period would be about **5 (Five)** working days.

Yours faithfully,

Constant Appraiser Services



Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA























