



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 6846T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	1,954.20	-
1	BONNET LOCK (CONSISTENT)	DAMAGED / DISTORTED	195.50	195.50
1	FRONT BUMPER (CONSISTENT)	DEFORMED	1,421.50	1,042.20
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	612.00	612.00
1	FRONT BUMPER REINFORCEMENT BRACKET LH (CONSISTENT)	BENT	112.50	112.50
1	HEADLAMP LH (CONSISTENT)	CRACKED	2,968.50	2,620.00
1	HEADLAMP BRACKET LH (CONSISTENT)	DAMAGED	102.00	102.00
1	HEADLAMP NOZZLE COVER LH (CONSISTENT)	DAMAGED	32.00	32.00
1	HEADLAMP NOZZLE HOSE LH (CONSISTENT)	DAMAGED	98.50	98.50
1	HEADLAMP NOZZLE PUMP LH (CONSISTENT)	DAMAGED	204.50	168.82
1	FRONT BUMPER FOG LAMP BRACKET LH (CONSISTENT)	BENT	85.90	85.90
1	FRONT FENDER LH (CONSISTENT)	TO REPAIR SEE LABOUR	652.30	-
1	FRONT FENDER INNER SHIELD LH (CONSISTENT)	DAMAGED	112.00	112.00
4	FRONT BUMPER PARKING SENSOR (CONSISTENT)	DAMAGED (1 PCS ONLY)	1,248.00	312.00
	LESS 5% DISCOUNT		-489.97	-274.67
			9,309.43	5,218.75
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER (SN) (CONSISTENT)	NECESSARY	55.00	55.00
1	FRONT BUMPER LOWER LID (SN) (CONSISTENT)	DAMAGED	610.00	610.00
			665.00	665.00
<u>LABOUR</u>				
	TO DISMANTLE, REPLACE ,CUT ,WELD ,KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF BONNET AND FRONT FENDER LH .		810.00	750.00
	PUTTY & SPRAY PAINTING TO ADJACENT PANELS .JOB ALLOWANCE .PAINT/MATERIAL.		800.00	750.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	APPLY RUST PROOFING ON THE ADJACENT PANELS.		30.00	30.00
	REMOVE AND REPLACE FRONT BUMPER PARKING SENSOR & CONDUCT DISTANCE SAFETY SETTING.		76.50	30.00
	SPECIALIST CHARGES -DIGNOSTIC FAULT CODE/RESET.		150.00	150.00
	WIRING AND BULB CHECKING.		36.00	30.00
			1,902.50	1,740.00
GRAND TOTAL			11,876.93	7,623.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,100.00

Report Ref No. CS3/ASM21001336/T1ps3q2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.