

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21006724/EVF3E2

Date: 07/07/2021

REFERENCE

Insured/Claimant:	NG ZHI QIN	Policy No:	1900079463		
Date of Loss:	14/06/2021	Nature of Claim:	OD	Claim No:	7131945490SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH5788G	Engine No:	G4FGJH716098
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5027530
Reg. Date:	25/03/2019 (Man. Year: 2018)	Odometer:	19707 km
Colour:	Black		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$74,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 5 mm	Rear Left Side:	Nexen 5 mm
Front Right Side:	Nexen 5 mm	Rear Right Side:	Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,290.80	3,761.60	2,529.20	40.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,340.00	3,510.00	3,830.00	52.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,630.80	7,271.60	6,359.20	46.65
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	13,330.80	6,971.60	6,359.20	47.70
+ GST 7.00/7.00% (S\$)	933.16	488.01	445.15	47.70
Nett Amount (S\$)	14,263.96	7,459.61	6,804.35	47.70

INSPECTION

Date of Assignment:	16/06/2021	
Date Inspected:	16/06/2021 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	6.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*LAMP ASSY-HEAD, LH	Cut	1,219.00 FL	*1,219.00 FL
3	1		*CARRIER ASSY-FRONT END MODULE	Not Necessary	675.00 FL	*- FL
4	1		*BEAM COMPLETE-FR BUMPER	Bent	497.00 FL	*497.00 FL
5	1		*PANEL ASSY-FRONT DOOR, RH	Dented	1,277.00 FL	*1,277.00 FL
6	1		*MOULDING ASSY-FRT DR FRAME, RH	Necessary	37.00 FL	*37.00 FL
7	1		*W/STRIP ASSY-FR DR BELT O/S RH	Not Necessary	64.00 FL	*- FL
8	1		*W/STRIP ASSY-FR DR SIDE RH	Not Necessary	102.00 FL	*- FL
9	1		*HANDLE ASSY-DOOR OUTSIDE, RH	Cut	164.00 FL	*164.00 FL
10	1		*GUARD ASSY-FRONT WHEEL, RH	Not Necessary	95.00 FL	*- FL
11	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
12	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
13	1		*GRILLE ASSY-RADIATOR	Not Necessary	328.00 FL	*- FL
14	1		*GARNISH-RADIATOR GRILLE	Not Necessary	38.00 FL	*- FL
15	1		*GRILLE-FRONT BUMPER	Broken	262.00 FL	*262.00 FL
16	1		*LAMP ASSY-FRONT FOG, LH	Bent	303.00 FL	*303.00 FL
17	1		*MOULDING-FRONT BUMPER, LH	Cut	36.00 FL	*36.00 FL
18	1		*LAMP ASSY-SIDE REPEATER, LH	Cut	143.00 FL	*143.00 FL
19	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	84.00 FL	*- FL
20	1		*AIR DUCT-FR BUMPER, LH	Not Necessary	14.00 FL	*- FL
21	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
22	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
23	1		*PANEL ASSY-HOOD	Not Necessary	1,502.00 FL	*- FL
24	1		*HINGE ASSY-HOOD, RH	Not Necessary	43.00 FL	*- FL
25	1		*HINGE ASSY-HOOD, LH	Not Necessary	43.00 FL	*- FL
26	1		*BLACK TAPE,FR DR RR,RH (Supplementary)	Necessary	13.00 FL	*13.00 FL
27	1		*COVER-FR BUMPER FOG LAMP, LH (Supplementary)	Cut	15.00 FL	*15.00 FL
28	10		*CLIP (Supplementary)	Necessary	20.00 FL	*20.00 FL
29	1		*COOLANT (4L) (Supplementary)	Necessary	26.00 FL	*26.00 FL
					Sub Total (\$\$)	7,851.00 4,697.00
					- List Item Discount on L Items 20.00/20.00% (\$\$)	1,560.20 935.40
					Total Parts (\$\$)	6,290.80 3,761.60

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE FRT BUMPER, SUPPORT, FRT RH DOOR, BONNET & AFFECTED AREA. REPAIR ON REAR RH DOOR, BOTH FRT FENDER & BOTH FRT BODY CHASSIS	New	2,800.00	800.00
2	PAINT WORK ON FRT BUMPER, BONNET, BOTH FRT FENDER, FRT RH DOOR, REAR RH DOOR & BOTH FRT CHASSIS	New	2,800.00	1,050.00
3	TO TRANSFER FRT RH DOOR ATTACHMENTS TO NEW PANEL	New	120.00	120.00
4	PERFORM RUST PREVENTION	New	120.00	40.00
5	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	SPRAY PAINT ON BONNET & FRONT RH FENDER (Supplementary)	New	700.00	700.00
8	SUPPLY FRONT NUMBER PLATE WITH FRAME (Supplementary)	New	50.00	50.00
9	VACUUM & TOP UP AIRCON GAS (Supplementary)	New	80.00	80.00
10	REPAIR FRONT BOTH CHASSIS (Supplementary)	New	400.00	400.00
11	REMOVE & REFIT AIRCON CONDENSER AND RADIATOR (Supplementary)	New	120.00	120.00
Gross Labour Cost (\$\$)			7,340.00	3,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >