

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21006726/APS3Q2
Date: 18/10/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900254704
Claimant Vehicle No :	FY6946D	Insured Vehicle No :	SMR2703T
Date of Loss:	10/06/2021	Nature of Claim:	TP
		Claim No:	0601009637SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FY6946D	Engine No:	VLX2M0013195
Make & Model:	HONDA ACCORD, 1.6 (M)	Chassis No:	ZAPM0940100003313
Reg. Date:	03/12/2004 (Man. Year: 2004)	Odometer:	136891 km
Colour:	Blue		
Engine Capacity:	151 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	110/70 R12	Rear Tyre Size:	120/70 R12
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,853.50	2,897.50	2,956.00	50.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,260.00	1,280.00	980.00	43.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,113.50	4,177.50	3,936.00	48.51
Approved Total (Overridden) (S\$)		3,300.00		

Nett Amount (S\$)	8,113.50	3,300.00	4,813.50	59.33
+ Loss of Use (10.0 x S\$20.00/day) (S\$)		200.00		
+ Other Costs (S\$)		50.00		
Nett Liability (S\$)		3,550.00		

INSPECTION

Date of Assignment: 16/06/2021

Date Inspected: 16/06/2021

Estimated Period of Repair: 9.0 days

Inspected At:

Erofia Motor Trading Pte Ltd (KAKI BUKIT)
 1 KAKI BUKIT AVE 6 #02-62
 Singapore 417883

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Distorted	145.00 FL	*145.00 FL
2	1		*FRONT FORK ASSY	Serviceable	950.00 FL	*- FL
3	1		*FRONT SHOCK ABSORBER	Bent	680.00 FL	*300.00 FL
4	1		*FRONT FORK COVER	Damaged	85.00 FL	*85.00 FL
5	1		*FRONT RIM	Not Necessary	180.00 FL	*- FL
6	1		*FRONT BRAKE DISC	Not Necessary	220.00 FL	*- FL
7	1		*TOP COWLING	Cracked	165.00 FL	*165.00 FL
8	1		*FRONT CENTRE COWLING	Dented	180.00 FL	*180.00 FL
9	1		*FRONT PANEL MOULDING	Cut	160.00 FL	*160.00 FL
10	1		*FRONT LIVING MOULDING	Not Necessary	180.00 FL	*- FL
11	1		*HEADLAMP	Cracked	180.00 FL	*180.00 FL
12	1		*METER ASSY	Not Necessary	480.00 FL	*- FL
13	1		*SET FRONT SIGNALS	Cracked	170.00 FL	*170.00 FL
14	1		*SET SIDE MIRRORS	Missing	160.00 FL	*160.00 FL
15	1		*HANDLE -BAR	Bent	235.00 FL	*235.00 FL
16	1		*SET HAND GRIP	Not Necessary	65.00 FL	*- FL
17	1		*BRAKE LEVER	Cut	450.00 FL	*45.00 FL
18	2		*ENGINE COVER	Dented	65.00 FL	*250.00 FL
19	2		*ENGINE COVER MOULDING	Cut	250.00 FL	*65.00 FL
20	1		*KICK STARTER	Cut	130.00 FL	*130.00 FL
21	1		*GRAR SELECTOR	Damaged	150.00 FL	*150.00 FL
22	1		*SET REAR SIGNALS	Cracked	160.00 FL	*160.00 FL
23	1		*REAR SHOCK ABSORBER	Bent	680.00 FL	*300.00 FL
24	1		*REAR TAILLAMP	Cracked	135.00 FL	*135.00 FL
25	1		*SET NUMBER PLATE	Dented	28.00 FS	*28.00 FS
26	1		*SET STEERING CONE	Necessary	96.00 FS	*96.00 FS
27	1		*VESPA EMBLEM	Necessary	100.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,479.00	3,199.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	625.50	301.50
Total Parts (\$\$)	5,853.50	2,897.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PROVIDE TOWING SERVICE (LOD)	New	50.00	50.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	50.00
3	TO PROVIDE SPRAY PAINT WORK	New	1,200.00	500.00
4	TO REPAIR BODY FRAME	New	450.00	300.00
5	TO PROVIDE LABOUR	New	480.00	380.00
Gross Labour Cost (S\$)			2,260.00	1,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >