



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. WBA7T22060CE22268

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|----------------------------------------------------------------------------------------------|---------------------------------------------|-----------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | USED FRONT FENDER LEFT (SN) | BENT | 300.00 | 300.00 |
| 1 | USED FRONT BUMPER (SN) | MISSING | 480.00 | 380.00 |
| 1 | USED REAR BUMPER (SN) | MISSING | 450.00 | 350.00 |
| 4 | FRONT BUMPER SUPPORT BRACKETS @\$22.06 (SN) | MISSING | 88.24 | 88.24 |
| 1 | USED FRONT GRILL (SN) | MISSING | 250.00 | 250.00 |
| 1 | USED FRONT WHEEL ARC (SN) | CRACKED | 80.00 | 80.00 |
| 1 | USED FRONT BONNET (SN) | BENT | 450.00 | 400.00 |
| 1 | IMPACT ABSORBER (SN) | CRACKED | 81.00 | 81.00 |
| | | | 2,179.24 | 1,929.24 |
| LABOUR | | | | |
| TO INSTALL DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(REAR BUMPER,FRONT BUMPER,BONNET). | | | 700.00 | 600.00 |
| TO CHECK WIRING. | | | 100.00 | 50.00 |
| TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING. | | | 120.00 | 60.00 |
| SPRAY PAINTING. | | | 1,500.00 | 1,200.00 |
| | | | 2,420.00 | 1,910.00 |
| GRAND TOTAL | | | 4,599.24 | 3,839.24 |
| RECOMMENDED COST OF REPAIRS | | | | 3,839.24 |

Report Ref No. CI/TP21006730/Kqe2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.