

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21006731/AUCE2**Date:** 12/10/2021**REFERENCE**

Insured/Claimant:	SEETOH KOK NGIN	Policy No:	1800097725	
Date of Loss:	11/06/2021	Nature of Claim:	OD	Claim No: 6638100102SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKN8191A		
Make & Model:	AUDI A6, 1.8 TFSI Ultra (PI) (NAV) (A)	Engine No:	CYG024301
Reg. Date:	15/08/2018 (Man. Year: 2017)	Chassis No:	WAUZZZ4G8JN054124
Colour:	Blue	Odometer:	50382 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	S\$177,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,190.00	5,479.20	13,710.80	71.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,352.00	4,982.00	14,370.00	74.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,542.00	10,461.20	28,080.80	72.86
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	38,142.00	10,061.20	28,080.80	73.62
+ GST 7.00/7.00% (S\$)	2,669.94	704.28	1,965.66	73.62
Nett Amount (S\$)	40,811.94	10,765.48	30,046.46	73.62

INSPECTION

Date of Assignment:	16/06/2021		
Date Inspected:	15/06/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	7.0 days		

Adjuster: ADRIAN LING**Manager:** Tan Hui Zhen

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	3,268.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	273.00 FS	*- FS
3	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	66.00 FS	*- FS
4	1		*REAR BUMPER GUIDE SECTION - LH	Not Necessary	53.00 FS	*- FS
5	1		*REAR FENDER	Repair	4,532.00 FS	*- FS
6	1		*REAR WINDSCREEN	Not Necessary	1,174.00 FS	*- FS
7	1		*REAR QUARTER GLASS	Not Necessary	390.00 FS	*- FS
8	1		*DOOR ENTRANCE STRIP	Not Necessary	120.00 FS	*- FS
9	1		*REAR WHEEL HOUSING LINER - LH	Not Necessary	275.00 FS	*- FS
10	1		*REAR WHEEL HOUSING LINER ATTACHMENT PARTS LH	Not Necessary	73.00 FS	*- FS
11	1		*SIDE PANEL TRIM LH	Deformed	858.00 FS	*686.40 FS
12	1		*SIDE PANEL END CAP LH	Not Necessary	88.00 FS	*- FS
13	1		*STONE GUARD FILM LH FRONT	Not Necessary	118.00 FS	*- FS
14	1		*SIDE PANEL TRIM ATTACHMENT CLIP LH	Necessary	89.00 FS	*71.12 FS
15	1		*SIDE PANEL TRIM ATTACHMENT TAPE LH	Necessary	16.00 FS	*12.48 FS
16	1		*REAR DOOR LH	Dented	4,227.00 FS	*3,381.60 FS
17	1		*REAR DOOR ATTACHMENT PARTS LH	Not Necessary	84.00 FS	*- FS
18	1		*REAR DOOR OUTER SEAL LH	Necessary	231.00 FS	*184.40 FS
19	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
20	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
21	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
22	1		*REAR DOOR SEAL LH - OUTER	Not Necessary	283.00 FS	*- FS
23	1		*REAR ALUMINIUM RIM LH	Cut	1,297.00 FS	*1,037.60 FS
24	1		*1/ GLASS SEALANT	Not Necessary	100.00 FS	*- FS
25	1		*ACRYLIC SEALANT	Not Necessary	180.00 FS	*- FS
26	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
27	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
28	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
29	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
30	1		*SUNDRIES	Necessary	350.00 FS	*105.60 FS
31	1		*REAR DOOR CATCH LH	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 19,190.00 5,479.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID CHECK FUNCTION	New	280.00	280.00
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	0.00
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND LHS 1/4 GLASS	New	400.00	0.00
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN AND 1/4 GLASS	New	200.00	0.00
5	TO DISLODGE & REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE & RELAY TRAYS, ELECTRICAL & AUDIO EQUIPMENT. INSPECT FOR DAMAGE & RENEW WHERE NECESSARY	New	1,400.00	0.00
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
7	TO DISMANTLE AND RENEW REAR BUMPER, LHS REAR DOOR AND LHS SILL PANEL TRIM. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	7,200.00	1,750.00
8	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, LHS SILL PANEL TRIM, LHS SILL PANEL, ROOF CHANNEL, DRAIN CHANNEL, DOOR ENTRANCE AND REAR END PANELLING	New	7,000.00	2,200.00
9	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
11	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	280.00
Gross Labour Cost (\$)			19,352.00	4,982.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >