

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

idac

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3292D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT FENDER HYBRID EMBLEM RH	NECESSARY	86.50	86.50
1	FRONT FENDER SUB ASSY RH	BENT	945.30	945.30
1	FRT FENDER RETAINER RH	CRACKED	86.30	86.30
1	FRONT FENDER SHIELD RH	DEFORMED	198.35	198.35
1	FRONT FENDER SHIELD CLIPS	NECESSARY	38.00	38.00
1	FRT WHEEL HUB CAP RH	CUT	177.70	177.70
1	FRT PILLAR UPP COVER RH	MISSING	96.00	96.00
1	FRONT BUMPER COVER	DEFORMED	499.90	499.90
1	FRONT BUMPER SIDE BRACKET RH	CRACKED	82.30	82.30
10	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRONT BUMPER FOG LAMP	CRACKED	920.00	920.00
1	HEADLAMP RH	CRACKED	2,637.60	2,637.60
1	WIPER SPARE TANK	DEFORMED	181.80	181.80
	LESS 25% DISCOUNT		-1,492.94	-1,492.94
			4,478.81	4,478.81
	SPECIAL NETT ITEMS			
1	FRT WHEEL TYRE RH (80%)(SN)	сит	216.00	172.80
			216.00	172.80
	<u>LABOUR</u>			
	PANEL BEATING.		1,100.00	525.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	WIRING CHARGE.		50.00	30.00
	TUFF KOTE.		60.00	30.00
	FRONT WHEEL ALIGNMENT.		80.00	80.00
			1,890.00	1,165.00
	GRAND TOTAL		6,584.81	5,816.61





Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,650.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. NS/INC21006733/T1tcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser