

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4357D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRT BUMPER ASSY	CRACKED	430.95	430.90
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT BUMPER BRACKET LH	NOT NECESSARY	35.00	-
1	FRT FENDER LH	BENT	588.80	588.80
1	FRT FENDER EMBLEM LH	NECESSARY	26.60	26.60
	LESS 20% DISCOUNT		-220.67	-213.66
			882.68	854.64
	<u>LABOUR</u>			
	PANEL BEATING.		800.00	350.00
	SPRAY PAINT.		600.00	500.00
	WIRING.	NOT NECESSARY	50.00	-
			1,450.00	850.00
	GRAND TOTAL		2,332.68	1,704.64

RECOMMENDED COST OF REPAIRS (CONFIRMED)		1,704.64

Report Ref No. NS/INC21006738/T1qcn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.