

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
WOO KOK LEUNG, ANDY (HU GUOLIANG)	Cust No/Name	LCV10633/WOO KOK LEUNG, ANDY (HU GUOLIAN)
BLK 463 ANG MO KIO AVENUE 10	Reg No/Reg Date	SMM9984D*KC17/ 23/07/201
#07-1104	Date In/Mileage	/ 0
SINGAPORE 560463	Chassis No	KNAD6811VL6319543
Contact No Mobile: 98567497	Engine No	G3LCKP068144
	Make/Model	KIA/STONIC 1.0 A SX BJ3 W SUNROOF
	Colour/Trim	MYW MOST YELLOW / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	16/06/2021/ 11:00	TLE	261 / Edwin Caina	34536

Description of Goods / Services		Qty	Unit Price	Disc%	Amount
E	PNT88000 TO RENEW RHF DOOR REPAIR RH CENTRE PILLAR				1920.00
E	PNT98000 RESPRAY RHF DOOR & RH CENTRE PILLAR				1100.00
E	PNT88000 REMOVE & REFIT RHF DOOR COMPONENTS				320.00
A	54900099 CHECK WIRING ELECTRICAL SYSTEM				80.00
A	10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				280.00
M	SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				80.00
M	SUNDRY SUPPLY BODY PNL SEALANT				80.00
M	SUNDRY Sundries				50.00
M	PANEL ASSY-FRONT DOOR,RH	1.00	858.00	00.00	858.00
M	PAD-DOOR O/S HANDLE REAR,RH	1.00	1.00	00.00	1.00
M	HANDLE ASSY-DOOR OUTSIDE,RH	1.00	124.00	00.00	124.00
M	COVER-FR DR O/S HDL RH	1.00	17.00	00.00	17.00
M	PAD-DOOR OUTSIDE HANDLE,RH	1.00	1.00	00.00	1.00
M	BASE ASSY-FR DR O/S HANDLE RH	1.00	27.00	00.00	27.00
M	LATCH ASSY-FRONT DOOR,LH	1.00	178.00	00.00	178.00
M	BLACK TAPE-FR DR FRAME UPR,RH	1.00	13.00	00.00	13.00
M	TAPE-FR DR BLACK FRAME RR,RH	1.00	13.00	00.00	13.00
M	MOULDING ASSY-SIDE SILL,RH	1.00	248.00	00.00	248.00
M	GARNISH ASSY-FR DR SIDE RH	1.00	82.00	00.00	82.00

SURVEYOR NAME : _____

Confirm & accepted by

SURVEYOR SIGNATURE: _____

DATE :

REMARKS :

	Nett	5,472.00
7% GST on	5472.00	383.04

Total Payable	5,855.04
----------------------	-----------------

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.