

| | | | | | | | | | | | |
|---|---|---|--------|---|---|---|---|------|---|---|-------------|
| ⏪ | < | 1 | of 2 ? | > | ⏩ | ↺ | ↻ | 100% | ⏴ | ⏵ | Find Next |
|---|---|---|--------|---|---|---|---|------|---|---|-------------|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|---|--|--------------------------|----------------|
| SMRT AUTOMOTIVE SERVICES PTE LTD | | Ref: CS/SMR21006754/Guf3 | |
| 60 WOODLANDS INDUSTRIAL PARK | | Date: 16/06/2021 | |
| E4SINGAPORE 757705 | | Code: SMR | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SHB 1013B | Veh. Inspected | GBD 1452C |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | TAX/06/21/2024 | Excess (\$) | 0.00 |
| Assign From | HUA YEN | Assign Date | 16/06/2021 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 12/06/2021 | Inspection Date | 16/06/2021 |
| Survey held at | YONG SING MOTOR WORKS 10 DEFU LANE 8 DEFU INDUSTRIAL ESTATE SINGAPORE 539315 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |