

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT |   |                         |                |       |                         |  |
|------------------------------|---|-------------------------|----------------|-------|-------------------------|--|
|                              | SMRT AUTOMOTI   | VE SERVICES PTE LTD     |                | Ref:  | CS3/SMR21006755/Vuf3e2  |  |
|                              | 60 WOODLANDS I<br>E4SINGAPORE 75  | NDUSTRIAL PARK<br>7705  |                | Date: | 21/06/2021              |  |
|                              |   |                         |                | Code: | SMR                     |  |
| 1.                           | Policy Particulars :- (THIRD PARTY CLAIM)   |                         |                |       |                         |  |
|                              | Insured Veh.  | SMB 1415R               | Veh. Inspected | k     | SJC 1662Z               |  |
|                              | Policy No.  |                         | Coverage (\$)  |       | 0.00                    |  |
|                              | Claim No.   | BUS/06/21/1028          | Excess (\$)    |       | 0.00                    |  |
|                              | Assign From   | HUA YEN                 | Assign Date    |       | 16/06/2021              |  |
| 2.                           | 2. Vehicle Particulars & Condition  |                         |                |       |                         |  |
|                              | Make & Model  | TOYOTA PRIUS AUTO       | c.c            |       | 1497                    |  |
|                              | Engine No.  | HIDDEN                  | Year of Reg.   |       | 2008                    |  |
|                              | Chassis No.   | JTDKB20U307726265       | Colour         |       | BLUE                    |  |
|                              | Odometer  | 511491 KM               | Steering       |       | IN ORDER                |  |
|                              | Brakes  | JAMMED                  | Modification   |       | STANDARD ALLOY RIM      |  |
|                              | General   | FAIR                    |                |       |                         |  |
| 3. Conditions of Tyres       |   |                         |                |       |                         |  |
|                              |   | Size                    | Make           |       | Balance                 |  |
|                              | R/H Front Tyre  | 195/60 R16              | NEXEN          |       | 5 mm                    |  |
|                              | L/H Front Tyre  | 195/60 R16              | NEXEN          |       | 5 mm                    |  |
|                              | R/H Rear Tyre   | 195/60 R16              | NEXEN          |       | 5 mm                    |  |
|                              | L/H Rear Tyre   | 195/60 R16              | NEXEN          |       | 5 mm                    |  |
| 4.                           | . Description of Damages  |                         |                |       |                         |  |
|                              | THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.  |                         |                |       |                         |  |
| 5. General Information       |   |                         |                |       |                         |  |
|                              | Accident Date   | 15/06/2021              | Inspect Date / | Time  | 16/06/2021 ( 05:00 PM ) |  |
|                              | Survey held at  | KIM SENG TECK MOTOR WOR | KS             |       |                         |  |
|                              | BLK 3021A UBI ROAD 1 #01-42 SINGAPORE 408715  |                         |                |       |                         |  |
| 5a.                          | Remarks   |                         |                |       |                         |  |
|                              | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$8,000-\$9,000 |                         |                |       |                         |  |
| 5b.                          | 5b. Estimate Days of Repair   |                         |                |       |                         |  |
|                              | ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days   |                         |                |       |                         |  |

Report Ref No. CS3/SMR21006755/Vuf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser