

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/GRB21006758/KBS3Q2  
**Date:** 03/08/2021**REFERENCE**

|                              |                                       |                             |                 |
|------------------------------|---------------------------------------|-----------------------------|-----------------|
| Handling Insurer:            | India International Insurance Pte Ltd | Policy No:                  | D21MFL0000447   |
| <b>Claimant Vehicle No :</b> | SJS8192H                              | <b>Insured Vehicle No :</b> | SLN4524M        |
| Date of Loss:                | 14/06/2021                            | Nature of Claim:            | TP              |
|                              |                                       | Claim No:                   | MFL2021D0002552 |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SJS8192H</b>                   |             |                   |
| Make & Model:               | TOYOTA COROLLA ALTIS, 1.6 CVT (A) | Engine No:  | 3ZZ4924796        |
| Reg. Date:                  | 08/09/2009 (Man. Year: 2009)      | Chassis No: | MR053ZEE106153110 |
| Colour:                     | Metallic Silver                   | Odometer:   | 274487 km         |
| Engine Capacity:            | 1598 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

**CONDITION OF TYRES**

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 195/65 R15    | Rear Tyre Size:  | 195/65 R15    |
| Front Left Side:  | Michelin 7 mm | Rear Left Side:  | Michelin 7 mm |
| Front Right Side: | Michelin 7 mm | Rear Right Side: | Michelin 7 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 5,089.65          | 4,235.05          | 854.60            | 16.79         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 2,105.00          | 1,670.00          | 435.00            | 20.67         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>7,194.65</b>   | <b>5,905.05</b>   | <b>1,289.60</b>   | <b>17.92</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>4,700.00</b>   |                   |               |

|                                                 |                 |                 |                 |              |
|-------------------------------------------------|-----------------|-----------------|-----------------|--------------|
| (S\$)                                           | 7,194.65        | 4,700.00        | 2,494.65        | 34.67        |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 503.63          | 329.00          | 174.63          | 34.67        |
| <b>Nett Amount (S\$)</b>                        | <b>7,698.28</b> | <b>5,029.00</b> | <b>2,669.28</b> | <b>34.67</b> |
| <b>+ Loss of Use (7.0 x S\$60.00/day) (S\$)</b> |                 | 420.00          |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                 | 7.45            |                 |              |
| <b>Nett Liability (S\$)</b>                     |                 | <b>5,456.45</b> |                 |              |

INSPECTION

Date of Assignment: 16/06/2021

Date Inspected: 17/06/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Alan's United Auto Pte Ltd (HQ)  
 Blk 7 Sin Ming Industrial Estate, #01-76  
 Singapore 575642

**Adjuster:** KENNETH KONG**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                                    |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 14 Jul 2021)                      |
| <b>Parts:</b>        | 143                                                                                                                                                                          | TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                                  |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SJS8192H)                                                                                                                                    |                                                                    |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                                    |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                                    |

### Recommended Parts

| No. | Qty | Part No. | Particulars                     | Condition        | Repairer's | Amount     |
|-----|-----|----------|---------------------------------|------------------|------------|------------|
| 1   | 1   |          | *FRONT N/S DOOR                 | Bent             | 891.90 FL  | *891.90 FL |
| 2   | 1   |          | *FRONT N/S DOOR PROTECTOR       | Dented           | 104.30 FL  | *104.30 FL |
| 3   | 1   |          | *FRONT N/S DOOR MOULDING        | Necessary        | 21.20 FL   | *21.20 FL  |
| 4   | 1   |          | *FRONT N/S DOOR INNER LOCK      | Repair           | 488.50 FL  | *- FL      |
| 5   | 1   |          | *FRONT N/S DOOR RUBBER (50%)    | Cut              | 118.28 FS  | *78.85 FS  |
| 6   | 1   |          | *FRT N/S DOOR REGULATOR GEAR    | Distorted        | 194.80 FL  | *194.80 FL |
| 7   | 1   |          | *SET FRONT N/S DOOR FRAME TAPE  | Necessary        | 70.20 FL   | *70.20 FL  |
| 8   | 1   |          | *N/S CENTRE PILLAR              | Repair           | 346.70 FL  | *- FL      |
| 9   | 1   |          | *N/S ROCKER GARNISH             | Dented / Cut     | 655.30 FL  | *655.30 FL |
| 10  | 1   |          | *REAR N/S DOOR                  | Bent             | 806.80 FL  | *806.80 FL |
| 11  | 1   |          | *REAR N/S DOOR PROTECTOR        | Bent             | 76.20 FL   | *76.20 FL  |
| 12  | 1   |          | *RR N/S DOOR PROTECTOR MOULDING | Necessary        | 21.20 FL   | *21.20 FL  |
| 13  | 1   |          | *SET REAR N/S DOOR FRAME TAPE   | Necessary        | 64.30 FL   | *64.30 FL  |
| 14  | 1   |          | *REAR N/S DOOR INNER LOCK       | Dented           | 424.70 FL  | *424.70 FL |
| 15  | 1   |          | *REAR N/S DOOR RUBBER (50%)     | Distorted / Cut  | 111.15 FS  | *74.10 FS  |
| 16  | 1   |          | *REAR N/S DOOR REGULATOR GEAR   | Bent             | 194.80 FL  | *194.80 FL |
| 17  | 1   |          | *REAR N/S DOOR REGULATOR MOTOR  | Jammed           | 662.20 FL  | *662.20 FL |
| 18  | 1   |          | *REAR N/S DOOR INNER TRIM COVER | Dented / Buckled | 733.20 FL  | *733.20 FL |
| 19  | 1   |          | *REAR N/S DOOR SPEAKER          | Serviceable      | 202.30 FL  | *- FL      |
| 20  | 2   |          | *REAR N/S DOOR HINGE            | Distorted        | 164.20 FL  | *164.20 FL |
| 21  | 1   |          | *REAR N/S DOOR CHECKER          | Distorted        | 146.70 FL  | *146.70 FL |
| 22  | 1   |          | *REAR N/S DOOR WINDOW SWITCH    | Dented           | 128.20 FL  | *128.20 FL |
| 23  | 1   |          | *REAR N/S DOOR OUTER HANDLE     | Distorted        | 82.60 FL   | *82.60 FL  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>6,709.73</b> | <b>5,595.75</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | 1,620.08        | 1,360.70        |

Report was unsubmitted during this print-out.

| No.                | Qty | Part No. | Particulars | Condition | Repairer's | Amount   |
|--------------------|-----|----------|-------------|-----------|------------|----------|
| Total Parts (\$\$) |     |          |             |           | 5,089.65   | 4,235.05 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                                                                                      | Lab.Type | Repairer's      | Amount          |
|--------------------------------|--------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <u>Labour Items</u>            |                                                                                                  |          |                 |                 |
| 1                              | TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET                               | New      | 180.00          | 100.00          |
| 2                              | TO APPLY UNDERSEALING                                                                            | New      | 60.00           | 60.00           |
| 3                              | TO CHECK AND ADJUST WHEEL ALIGNMENT                                                              | New      | 65.00           | 60.00           |
| 4                              | TO PUTTY AND SPRAY REPLACED PARTS                                                                | New      | 1,000.00        | 800.00          |
| 5                              | TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS | New      | 800.00          | 650.00          |
| <b>Gross Labour Cost (S\$)</b> |                                                                                                  |          | <b>2,105.00</b> | <b>1,670.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >