



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2108384

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 06/12/2021
Reference CC4/FCI21006759/T1ra3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. GBF 5938G
Insured Veh. GBF 344C
Claim No. D21001806MFCV
Policy No. D-21097023MFCV
Accident Date 14/06/2021
Inspection Date 16/06/2021

Description	Total
Survey Inspection	313.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	313.00
GST (7%)	21.91
Grand Total	334.91

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21006759/T1ra3q2	
			Date: 06/12/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 344C	Veh. Inspected	GBF 5938G	
Policy No.	D-21097023MFCV	Coverage (\$)	0.00	
Claim No.	D21001806MFCV	Excess (\$)	0.00	
Assign From	CHRIS	Assign Date	16/06/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN CABSTAR	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JN1SC2F24Z0859120	Colour	WHITE	
Odometer	67604 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	HONOUR	6 mm	
L/H Front Tyre	195 R15	HONOUR	6 mm	
R/H Rear Tyre	155 R13 (D)	HONOUR	6/6 mm	
L/H Rear Tyre	155 R13 (D)	HONOUR	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/06/2021	Inspection Date	16/06/2021	
Survey held at	ZOOM AUTOWERKS PTE LTD 832 SIMS AVENUE #12-884 EUNOSVILLE SINGAPORE 400832			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 5938G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR SIDE FRIDGE PANEL RH (W/INSULATOR) (SN)	TO REPAIR SEE LABOUR	3,280.00	-
1	REAR SIDE FRIDGE DOOR RH (W/INSULATOR) (SN)	TO REPAIR SEE LABOUR	2,450.00	-
1	REAR SIDE FRIDGE DOOR LOWER HINGE RH (ALUMINIUM) (SN)	BENT	245.00	245.00
1	REAR SIDE FRIDGE DOOR WEATHERSTRIP RH (SN)	CUT	495.00	495.00
1	REAR SIDE FRIDGE DOOR FRAME RH (ALUMINIUM CLADDING-HORIZONTAL) (SN)	BENT	680.00	680.00
1	REAR SIDE FRIDGE DOOR FRAME RH -(ALUMINIUM CLADDING-VERTICAL) (SN)	BENT	720.00	720.00
1	REAR TAILLAMP RH (SN)	CRACKED	295.86	295.86
1	REAR TAILLAMP BRACKET RH (SN)	BENT	95.60	95.60
1	REAR REINFORCEMENT DAMPER RUBBER (SN)	CUT	175.00	175.00
			8,436.46	2,706.46
	<u>LABOUR</u>			
	TO REMOVE ,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS.INCLUSIVE OF THE REPAIR OF REAR SIDE FRIDGE PANEL RH (W/INSULATOR) AND REAR SIDE FRIDGE DOOR RH (W/INSULATOR).		1,500.00	800.00
	TO PUTTY ,SPRAY PAINT ON AFFECTED ACCIDENT AREAS .		800.00	500.00
	TO CHECK & RECONNECT ALL ELECTRICAL WIRING .		50.00	30.00
	TO CONDUCT WATER LEAKAGE TEST .		150.00	30.00
	TO RUST PROOF AFFECTED AREAS .		200.00	30.00
			2,700.00	1,390.00
GRAND TOTAL			11,136.46	4,096.46
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,250.00

Report Ref No. CC4/FCI21006759/T1ra3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 5938G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBF 5938G

RE-INSPECTION

