

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD CS3/ASM21006760/Vtce2 Ref: 8 SHENTON WAY #24-01 AXA Date: 23/06/2021 **TOWERSINGAPORE 068811** ATTN: ANG RICHARD Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHA 3376X GBK 5842Y** Veh. Inspected Policy No. VFX/P2419138 Coverage (\$) 0.00 Claim No. S1M03BNR Excess (\$) 0.00 ANG RICHARD **Assign Date** 16/06/2021 Assign From **Vehicle Particulars & Condition** 2. **TOYOTA HIACE 3.0M** Make & Model 2982 c.c HIDDEN 2020 Engine No. Year of Reg. JTFHT02P009990400 SILVER Chassis No. Colour Odometer 35434 KM Steering IN ORDER **IN ORDER** SPORTS RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195 R15C BRIDGESTONE 5 mm L/H Front Tyre 195 R15C BRIDGESTONE 5 mm 195 R15C BRIDGESTONE R/H Rear Tyre 5 mm **BRIDGESTONE** L/H Rear Tyre 195 R15C 5 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. 5. **General Information** 10/06/2021 16/06/2021 (04:00 PM) Inspect Date / Time Accident Date KWAN YING MUN MOTOR SERVICE Survey held at BLK 3023A UBI RD 1 #01-57 SINGAPORE 408717 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000

Report Ref No. CS3/ASM21006760/Vtce2

Estimate Days of Repair

Inspected By

5b.

THEVAN THOMAS KARTHIKESAVAN

ESTIMATED NORMAL PERIOD FOR REPAIR:

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

6 Working Days