

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CHINA TAIPING INSURANCE (S) PTE LTD CS3/CTI21006766/Bqce2 Ref: 3 ANSON ROAD #16-00 Date: 30/06/2023 SPRINGLEAF TOWERSINGAPORE 079909 Code: CTI 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SJG 944X PC 1115R Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. SNM21D203264/C02/SJG944X/ Excess (\$) 0.00 **CHEESC** CHEE SO CHOW 16/06/2021 **Assign From Assign Date** 2. **Vehicle Particulars & Condition** Make & Model TOYOTA HIACE 2982 Engine No. **HIDDEN** Year of Reg. Chassis No. KDH2010084867 Colour SILVER **IN ORDER** Odometer Steering **IN ORDER** NIL **Brakes** Modification GOOD General **Conditions of Tyres** 3. Size Make **Balance** 195/80 R15 BRIDGESTONE 6 mm R/H Front Tyre BRIDGESTONE L/H Front Tyre 195/80 R15 6 mm R/H Rear Tyre 195/80 R15 **BRIDGESTONE** 6 mm 195/80 R15 **BRIDGESTONE** L/H Rear Tyre 6 mm 4. **Description of Damages** THE VEHICLE HAD COMMENCED ITS REPAIR AT THE TIME OF INSPECTION. 5. **General Information Accident Date** 08/06/2021 **Inspect Date / Time** 17/06/2021 (04:05 PM) TEAM AUTOPRO PTE LTD Survey held at 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

Report Ref No. CS3/CTI21006766/Bqce2

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Inspected By

J. Mm

LIM TEOW GUAN

1

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser