

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006767/TGA3Q2**Date:** 14/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070124982
Claimant Vehicle No :	SLP3962C	Insured Vehicle No :	SMU7407A
Date of Loss:	14/06/2021	Nature of Claim:	TP
		Claim No:	7171153955SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP3962C	Engine No:	L15B5000221
Make & Model:	HONDA SHUTTLE, 1.5 G CVT (A)	Chassis No:	GK81100198
Reg. Date:	02/06/2017 (Man. Year: 2016)	Odometer:	75178 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dayton 6 mm	Rear Left Side:	Dayton 6 mm
Front Right Side:	Dayton 6 mm	Rear Right Side:	Dayton 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,367.32	5,911.62	5,455.70	47.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,700.00	2,540.00	5,160.00	67.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,067.32	8,451.62	10,615.70	55.67
Approved Total (Overridden) (S\$)		6,750.00		
(S\$)	19,067.32	6,750.00	12,317.32	64.60
+ GST 7.00/7.00% (S\$)	1,334.71	472.50	862.21	64.60
Nett Amount (S\$)	20,402.03	7,222.50	13,179.53	64.60
+ Car Rental (9.0 x S\$100.00/day + 7.00% GST) (S\$)		963.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,192.95		
Global Sum Settlement (S\$)		8,150.00		

INSPECTION

Date of Assignment:	16/06/2021	AP Automotive Services Pte Ltd
Date Inspected:	17/06/2021 Inspected At:	56 Loyang Way, #04-04 Loyang Enterprise Building
Estimated Period of Repair:	7.0 days	Singapore 508775

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	628.20 FL	*628.20 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	127.00 FL	*127.00 FL
3	2		*TAILGATE LAMP L+R (NPA)	Not Necessary	0.00 FL	*- FL
4	1		*TAILGATE OUTER GARNISH	Not Necessary	345.00 FL	*- FL
5	1		*TAILGATE CHROME	Not Necessary	386.00 FL	*- FL
6	1		*TAILGATE LOGO -HONDA	Necessary	79.00 FL	*79.00 FL
7	1		*TAILGATE HANDLE SWITCH	Not Necessary	268.00 FL	*- FL
8	1		*TAILGATE LOCK (NPA)	Not Necessary	0.00 FL	*- FL
9	1		*TAILGATE LOCK CATCH	Not Necessary	76.00 FL	*- FL
10	1		*TAILGATE INNER TRIM	Cut	238.00 FL	*238.00 FL
11	1		*SET TAILGATE HINGE	Not Necessary	190.00 FL	*- FL
12	1		*SET TAILGATE DAMPER	Not Necessary	360.00 FL	*- FL
13	1		*TAILGATE WEATHERSTRIP	Cut	150.00 FL	*150.00 FL
14	1		*TAIL LAMP L+R	N/S Cracked / O/SNot Necessary	843.12 FL	*421.56 FL
15	1		*TAIL LAMP PANEL L+R	N/S Damaged/O/S Not Necessary	428.00 FL	*214.00 FL
16	1		*REAR BUMPER	Deformed	1,150.00 FL	*1,150.00 FL
17	1		*REAR BUMPER REFLECTOR L+R	N/S Missing / O/SNot Necessary	142.00 FL	*71.00 FL
18	1		*REAR BUMPER REFLECTOR GARNISH L+R	N/S Missing / O/SNot Necessary	224.80 FL	*112.40 FL
19	1		*REAR BUMPER REFLECTOR SPONGE L+R	N/S Cracked /O/S Not Necessary	103.84 FL	*51.92 FL
20	1		*REAR BUMPER REVERSE SENSOR L+R	N/SNecessary/O/SNotNecessary	346.00 FL	*173.00 FL
21	1		*REAR BUMPER TOW COVER	Not Necessary	86.00 FL	*- FL
22	1		*REAR BUMPER RETAINER L+R	N/SDeformed/O/SNot Necessary	160.00 FL	*80.00 FL
23	1		*REAR BUMPER BRACKET	Deformed	105.00 FL	*105.00 FL
24	1		*REAR BUMPER UNDERCOVER	Not Necessary	472.00 FL	*- FL
25	1		*REAR FENDER LH	Bent	1,024.69 FL	*1,024.69 FL
26	1		*REAR FENDER INNER TRIM L+R	N/SDeformed/O/SNot Necessary	873.50 FL	*436.75 FL
27	1		*REAR FENDER COWLING L+R	N/SDeformed/O/SNot Necessary	212.00 FL	*106.00 FL
28	1		*END PANEL	Bent	492.60 FL	*492.60 FL
29	1		*END PANEL TOP GARNISH	Deformed	134.00 FL	*134.00 FL
30	1		*REAR SMART LOCK ANTENNA	Not Necessary	195.00 FL	*- FL
31	1		*REAR BUZZER	Cracked	146.00 FL	*146.00 FL
32	1		*SPAREWHEEL PANEL (NPA)	Repair	0.00 FL	*- FL
33	1		*SPAREWHEEL PANEL TOP BOARD	Deformed	439.40 FL	*439.40 FL
34	1		*SPAREWHEEL PANEL TOOLS SPONGE	Deformed	144.00 FL	*144.00 FL
35	1		*SPAREWHEEL PANEL ACCESSORIES TRAY	Deformed	411.00 FL	*411.00 FL
36	1		*SPAREWHEEL PANEL ACCESSORIES TRAY FRONT COVER	Deformed	179.00 FL	*179.00 FL
37	1		*TAILGATE WINDSCREEN SEALANT	Necessary	150.00 FS	*50.00 FS
38	1		*TAILGATE INNER TRIM CLIPS	Necessary	100.00 FS	*20.00 FS
39	1		*TAIL LAMP CLIPS	Necessary	50.00 FS	*20.00 FS
40	1		*TAIL LAMP PANEL SEALANT	Not Necessary	120.00 FS	*- FS
41	1		*REAR NUMBER PLATE	Not Necessary	120.00 FS	*- FS
42	1		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
43	1		*REAR FENDER SEALANT	Not Necessary	250.00 FS	*- FS
44	1		*REAR FENDER WINDOW SEALANT	Not Necessary	200.00 FS	*- FS
45	1		*REAR FENDER INNER PANEL SEALANT	Not Necessary	250.00 FS	*- FS
46	1		*REAR FENDER INNER TRIM CLIPS	Necessary	200.00 FS	*20.00 FS
47	1		*REAR FENDER COWLING CLIPS	Necessary	100.00 FS	*20.00 FS
48	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
49	1		*END PANEL SEALANT	Necessary	200.00 FS	*40.00 FS
50	1		*END PANEL TOP GARNISH CLIPS	Necessary	100.00 FS	*20.00 FS
51	1		*SPAREWHEEL PANEL SEALANT	Not Necessary	300.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$\$)	13,599.15
					- List Item Discount on L Items 20.00/20.00% (\$\$)	2,231.83
					Total Parts (\$\$)	11,367.32

7,334.52
1,422.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	2,400.00	1,200.00
2	SPRAYPAINT ON AFFECTED AREAS	New	1,600.00	1,000.00
3	TO RNR REAR WINDSCREEN	New	350.00	120.00
4	TO RNR REAR EXHAUST	New	250.00	0.00
5	TO CHECK WIRING AND TAILLAMP FUNCTION }	New	150.00	30.00
6	TO CHECK WIRING AND TAILGATE LAMP FUNCTION }	New	150.00	0.00
7	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	60.00
8	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	0.00
9	TO RNR UNDERCARRIAGE	New	250.00	0.00
10	TO CHECK WATER LEAK	New	150.00	0.00
11	TO RNR FUEL TANK	New	250.00	0.00
12	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
13	TO RNR REAR TAILGATE MECHANISM	New	350.00	60.00
14	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	150.00	30.00
15	TO PERFORM RUST PROOFING	New	400.00	40.00
Gross Labour Cost (\$\$)			7,700.00	2,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >