

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21006771/T1GA3Q2
Date: 14/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900018816
Claimant Vehicle No :	SHA2202X	Insured Vehicle No :	SMJ1716E
Date of Loss:	16/06/2021	Nature of Claim:	TP
		Claim No:	1628010092SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA2202X		
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Engine No:	G4LEKU404657
Reg. Date:	14/11/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVLU188830
Colour:	Blue	Odometer:	195542 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,159.92	1,023.24	136.68	11.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,640.00	1,135.00	505.00	30.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,799.92	2,158.24	641.68	22.92
+ GST 7.00/7.00% (S\$)	195.99	151.08	44.91	22.91

Nett Amount (S\$)	2,995.91	2,309.32	686.59	22.92
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$125.19/day) (S\$)		500.76		
(S\$)		3,010.08		
Liable Amount (80.00%) (S\$)		2,408.06		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,410.06		
Global Sum Settlement (S\$)		2,400.00		

INSPECTION

Date of Assignment: 16/06/2021

Date Inspected: 17/06/2021

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Deformed	459.40 FL	*459.40 FL	
2	1		*REAR BUMPER CENTRE MOULDING	Cut	451.25 FL	*451.25 FL	
3	1		*REAR BUMPER SIDE BRACKET RH	Not Necessary	55.80 FL	*- FL	
4	10		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL	
5	1		*REAR BUMPER REFLECTOR RH	Not Necessary	41.45 FL	*- FL	
6	1		*REAR WHEEL CAP RH	Cut	346.40 FL	*346.40 FL	
7	1		*REAR FENDER SHIELD RH	Not Necessary	73.60 FL	*- FL	
F=Franchise part. L=ListItemDisc.							
					Sub Total (\$\$)	1,449.90	1,279.05
					- List Item Discount on L Items 20.00/20.00% (\$\$)	289.98	255.81
					Total Parts (\$\$)	1,159.92	1,023.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING -REAR FENDER RH	New	800.00	525.00
2	SPARAY PAINTING	New	600.00	500.00
3	R/I REVERSE SENSOR	New	120.00	30.00
4	WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (\$)			1,640.00	1,135.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >