

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III21006774/T1BA3E2**Date:** 19/08/2021REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_01

Claimant Vehicle No : YQ8888S **Insured Vehicle No :** GBH7452S

Date of Loss: 15/06/2021 Nature of Claim: TP Claim No: MFL2021D0002596

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YQ8888S**

Make & Model: MITSUBISHI FUSO, 7.5 D FK62FMZ1RDEB (M) Engine No: 6M60216677

Reg. Date: 24/08/2016 (Man. Year: 2016) Chassis No: FK62FMA30163

Colour: White Odometer: 142336 km

Engine Capacity: 7545 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/70 R19.5 Rear Tyre Size: 245/70 R19.5 (D)

Front Left Side: Falken 8 mm Rear Left Side: Falken 8/8 mm

Front Right Side: Falken 8 mm Rear Right Side: Falken 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,567.48	7,246.86	3,320.62	31.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,725.00	3,280.00	1,445.00	30.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,292.48	10,526.86	4,765.62	31.16
Approved Total (Overridden) (S\$)		8,400.00		
Nett Amount (S\$)	15,292.48	8,400.00	6,892.48	45.07

INSPECTION

Date of Assignment: 16/06/2021

Date Inspected: 16/06/2021 Inspected At: Zoom Autowerks Pte Ltd (HQ)
15 Kaki Bukit Road 4, #01-53
Singapore 417808

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Aug 2021)	
Parts:	N/A	mitsubishi fuso 7.5 D FK62FMZ1RDEB (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ8888S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented/Bent/Distorted	1,303.00 FL	*1,303.00 FL
2	1		*FRONT BUMPER BRACKET LH	Dented/Bent	353.00 FL	*265.00 FL
3	1		*HEADLAMP ASSY LH	Broken	1,108.00 FL	*1,108.00 FL
4	1		*HEADLAMP RIM	Dented/Cracked	290.00 FL	*208.50 FL
5	1		*FOGLAMP ASSY LH	Broken	336.00 FL	*336.00 FL
6	1		*FRONT GRILLE	Cracked	684.00 FL	*684.00 FL
7	1		*FRONT GRILLE STAR LOGO	Necessary	78.00 FL	*78.00 FL
8	1		*FRONT GRILLE FIGHTER EMBLEM	Necessary	58.00 FL	*58.00 FL
9	1		*FRONT GRILLE LOWER TRIM PANEL	Bracket Squashed/Cracked	221.00 FL	*221.00 FL
10	4		*FRONT GRILLE LOWER TRIM PANEL CLIP	Necessary	24.00 FL	*24.00 FL
11	1		*FRONT BONNET	Dented/Bent	2,681.00 FL	*2,681.00 FL
12	1		*FRONT BONNET FUSE EMBLEM	Necessary	146.00 FL	*146.00 FL
13	1		*FRONT BONNET HINGE LH	Bent	124.00 FL	*124.00 FL
14	1		*FRONT CORNER PANEL LH	Dented/Mount Broken	578.00 FL	*578.00 FL
15	1		*FRONT SIGNAL LAMP LH	Cracked/Casing Broken	291.00 FL	*291.00 FL
16	1		*FRONT STEP PANEL LH	Not Necessary	246.00 FL	*- FL
17	1		*FRONT STEP PANEL GARNISH LH	Bent/Cracked	344.00 FL	*344.00 FL
18	1		*FRONT WHEEL ARCH GARNISH LH	Mount bracket broken	326.00 FL	*326.00 FL
19	1		*FRONT WHEELHOUSE PANEL	Repair	827.00 FL	*- FL
20	1		*FRONT WHEELHOUSE LINER	Squashed / Deformed	219.00 FL	*219.00 FL
21	1		*FRONT DOOR ASSY LH	Repair	3,185.00 FL	*- FL
22	1		*AIRCON CONDENSER	Dented	667.98 FL	*667.98 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	14,089.98	9,662.48
- List Item Discount on L Items 25.00/25.00% (S\$)	3,522.50	2,415.62
Total Parts (S\$)	10,567.48	7,246.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	45.00	30.00
2	TO APPLY ANTI-RUST UNDERCOAT	New	200.00	100.00
3	TO ALIGN HEADLAMPS AND REFOCUS HEADLAMP BEAMS	New	80.00	30.00
4	LABOUR CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO PANEL BEATING AFFECTED AND DAMAGED PARTS	New	2,100.00	1,200.00
5	SPRAY PAINTING CHARGES TO PAINT THE FRONT BUMPER, FRONT LH DOOR, FRONT WHEELHOUSE PANEL, FRONT WHEEL ARCH GARNISH, FRONT LH CORNER PANEL, HEADLAMP BASE PANEL, FRONT GRILLE LOWER TRIM PANEL, LH HEADLAMP RIM, FRONT BONNET AND NECESSARY AREAS	New	1,800.00	1,500.00
6	TO REMOVE AND REPLACE DAMAGED AIRCON CONDENSER AND TO VACUUM AND CHARGE UP AIRCON GAS	New	150.00	120.00
7	TO SUPPLY AND INSTALL FRONT BONNET AND FRONT DOOR ARTWORK AND COMPANY STICKERS	New	350.00	300.00
Gross Labour Cost (\$\$)			4,725.00	3,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >