



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBS 3747K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	REAR REVERSE LAMP;B9TL EU5	CRACKED	81.00	81.00
1	LED STOP/TAIL LIGHT 24V;30541713 1 LED	CRACKED	66.00	66.00
1	LED INDICATOR LIGHT 24V;30541714 1 LED	CRACKED	67.00	67.00
1	NUMBER PLATE RECESS PAN;EXT.RR	CRACKED	166.00	166.00
1	DOOR.LOWER BOOT	BENT	1,140.00	1,140.00
1	EMBLEM;DECALS	NECESSARY	48.00	48.00
2	DOOR RETAINER;EXTERIOR DOOR	BENT	15.00	15.00
1	CHECK STRAP.BOOT DOOR.RR	BENT	23.00	23.00
1	REAR A/C ACCESS DOOR ASSY;RR ENG DR	BENT	3,176.00	3,176.00
1	PLATE;2MX1M;SOUND ABSORBER	NECESSARY	466.00	466.00
			5,248.00	5,248.00
<b>LABOUR</b>				
	CONTRACTOR LABOUR.		1,050.00	1,050.00
			1,050.00	1,050.00
<b>GRAND TOTAL</b>			<b>6,298.00</b>	<b>6,298.00</b>
<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)</b>				<b>6,298.00</b>

Report Ref No. CS/FCI21006775/T1qf3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.