

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |   |                 |                   |             |  |
|---|--|---|-----------------|-------------------|-------------|--|
|   | LONPAC INSURAN   | ICE BHD                                   | Re              | : CS3/LPC21005419 | 9/T1vf3e2-1 |  |
|   | 300 BEACH ROAD<br>#17-04/07 THE CO   | NCOURSESINGAPORE 199555                   | Da              | e: 07/07/2021     |             |  |
|   |  |   | Со              | de: LPC2          |             |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM  |   |                 |                   |             |  |
|   | Insured Veh.   | XB 7892B                                  | Veh. Inspected  | XE 2658D          |             |  |
|   | Policy No.   |   | Coverage (\$)   | 0.00              |             |  |
|   | Claim No.  | 21/21/21/VC05/024528                      | Excess (\$)     | 0.00              |             |  |
|   | Assign From  | ONG LI LI                                 | Assign Date     | 17/06/2021        |             |  |
| 2. Vehicle Particulars & Condition                                |  |   |                 |                   |             |  |
|   | Make & Model   | MITSUBISHI FUSO FP51SD                    | c.c             | 11967             |             |  |
|   | Engine No.   | HIDDEN                                    | Year of Reg.    | 2017              |             |  |
|   | Chassis No.  | FP51SDA20139                              | Colour          | BLUE              |             |  |
|   | Odometer   | 314004 KM                                 | Steering        | IN ORDER          |             |  |
|   | Brakes   | IN ORDER                                  | Modification    | SPORTS RIM        |             |  |
|   | General  | FAIR                                      |                 |                   |             |  |
| 3.  | 3. Conditions of Tyres   |   |                 |                   |             |  |
|   |  | Size                                      | Make            | Balance           |             |  |
|   | R/H Front Tyre   | 295/80 R22.5                              | FIRENZA         | 6 mm              |             |  |
|   | L/H Front Tyre   | 295/80 R22.5                              | FIRENZA         | 6 mm              |             |  |
|   | R/H Rear Tyre  | 295/80 R22.5                              | FIRENZA         | 6 mm              |             |  |
|   | L/H Rear Tyre  | 295/80 R22.5                              | FIRENZA         | 6 mm              |             |  |
| 4. Description of Damages   |  |   |                 |                   |             |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  |   |                 |                   |             |  |
|   | DAMAGES SEE DETAILS.   |   |                 |                   |             |  |
| 5.  | General Information  |   |                 |                   |             |  |
|   | Accident Date  | 29/04/2021                                | Inspection Date | 05/05/2021        |             |  |
|   | Survey held at   | 24 SUNGEI KADUT ST 4, 729050 Sungei Kadut |                 |                   |             |  |
|   | Repairer   | airer LYS ENGINEERING                     |                 |                   |             |  |
| 5a.   | Remarks  |   |                 |                   |             |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                 |                   |             |  |
| 5b.   | Estimate Days of Repair  |   |                 |                   |             |  |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days   |   |                 |                   |             |  |