

# Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant\_as@yahoo.com.sg

RCB No. 53138015K

## Automobile Inspection Report

To: SG Sagawa Ameroid Pte Ltd 15 Pioneer Walk #02-01 Pioneer Hub Singapore 627753	Date : 14/05/2021 Reference No : CAS/21-05/015
<b><u>General Information</u></b>	
Registration No. : XE 2658D Accident Date : 29/04/2021	
<b><u>Particulars of Damaged Vehicle</u></b>	
Colour : Blue Engine Capacity : 11967 cc Mileage (KM) : 314023 Chassis No. : FP51SDA20139 Registration Date : 02/03/2017	Make & Model : Mitsubishi Fuso FP51SDR3VDEA Pre-Accident Condition : Good Engine No. : OM457329408 Steering : In Order Brake : In Order
<b><u>Tyre Condition</u></b>	
R/H Front Tyre L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	Size 295/80R22.5 295/80R22.5 295/80R22.5 (D) 295/80R22.5 (D)
Make KPATOS KPATOS KPATOS	Balance 80% 80% 90% / 90% 90% / 90%
<b><u>Inspection</u></b>	
Repairer : LYS Engineering 65 Chestnut Avenue, #18-15, Singapore 679524	
<b><u>Adjustment And Recommendation Cost Of Repair</u></b>	
Repairer's Estimate : \$24,834.21 Revised Amount : \$19,250.00 Less Excess : - Nett Total : \$19,250.00	
<b><u>Remarks</u></b>	
(A) Survey was done on 05/05/2021 (B) Re-survey was done on 06/05/2021 (C) Re-survey after repair was done on 10/05/2021 (D) The survey was conducted entirely on WITHOUT PREJUDICE basis. (E) We have NOT given any instruction to authorize the repair of the vehicle.	

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

**Adjustment On Repair Costs And Replacement Of Parts:**

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT – LIST ITEMS</u>			
1	1pc	Front panel (big)	Dented/Warped	4,852.80	4,852.80
2	2pcs	Front panel top hinge @ \$195.07	Bent/Twisted	390.14	390.14
3	2pcs	Front panel inner lock @ \$149.60	Bent/Jammed	299.20	299.20
4	2pcs	Front panel inner lock catch @ \$61.20	Bent	122.40	122.40
5	1pc	Front panel grille top	Broken	758.09	758.09
6	1pc	Front panel grille lower	Broken	926.24	926.24
7	1pc	Front panel inner cylinder absorber	Bent/Jammed	480.00	480.00
8	1pc	Front inner center lock bracket	Bent	198.63	198.63
9	1pc	Front Mitsubishi mark	Necessary	227.14	227.14
10	1pc	Front Mitsubishi emblem Fuso	Necessary	228.08	228.08
11	1pc	Front panel center inner latch	Bent/Twisted	389.09	389.09
12	1pc	Front bumper assy	Dented/Warped	3,688.09	3,688.09
13	1pc	Front bumper top step garnish center	Deformed	499.05	499.05
14	2pcs	Front bumper inner air duct @ \$189.02	Deformed	378.04	378.04
15	2pcs	Front bumper corner cover @ \$298.17	Broken	596.34	596.34
16	1pc	Front bumper top center panel	Dented/Broken	850.22	850.22
17	1pc	Front bumper top center panel inner reinforcement	Dented/Twisted	658.23	658.23
18	2pcs	Front bumper L & R garnish cover @ \$699.09	Broken	1,398.18	1,398.18
19	2pcs	Front corner panel @ \$996.07	Broken	1,992.14	1,992.14
20	2pcs	Front corner panel signal lamp @ \$296.63	Broken	593.26	593.26
21	2pcs	Front corner panel inner seal @ \$86.13	Necessary	172.26	172.26
22	2pcs	Front headlamp assy @ \$1,654.03	Broken	3,308.06	3,308.06
23	2pcs	Front headlamp inner aluminum bracket @ \$1,106.12	Bent/Twisted	2,212.24	2,212.24
24	2pcs	Front headlamp bezel @ \$298.09	Broken	596.18	596.18
25	2pcs	Front foglamp @ \$658.42	Broken	1,316.84	1,316.84
26	2pcs	Front lamp bezel @ \$389.56	Broken	779.12	779.12
27	1pc	Front right wiper spare water tank	Deformed	498.22	498.22
				28,408.28	28,408.28
		Less 25%		(7,102.07)	(7,102.07)
		Sub total		21,306.21	21,306.21

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		<u>PARTS REPLACEMENT – SPECIAL NETT ITEMS</u>			
1	1set	Front grille clip	Necessary	48.00	48.00
2	1pc	Front company wording	Necessary	280.00	220.00
			Sub total	21,634.21	21,574.21
		<u>LABOUR &amp; MISC. CHARGES</u>			
1		Labour to repair & replace front damaged parts		1,200.00	1,000.00
2		Spray painting on front affected area		1,500.00	1,200.00
3		Check front wiring system & refocus headlamp		80.00	40.00
4		Spray anti rust on affected area		120.00	60.00
5		Diagnose & reset system after repair		300.00	150.00
			Grand total	24,834.21	24,024.21
Recommended cost of lump sum repair (To its pre-accident condition)					19,250.00

**Adjustment/Recommendations**

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$19,250.00** on a contractual basis. Under normal circumstances, the repair period would be about **6 (Six)** working days.

Yours faithfully,

**Constant Appraiser Services**



Lim Yong Tian (Sebastian)

Licensed Appraiser

Adv. Dip. In Mechanical Engineering (AUS)

MSAAA