

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI21006777/VQCE2

Date: 01/07/2021

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00082372000

**Claimant Vehicle
No :** YN5727J

**Insured Vehicle
No :** SJU4131A

Date of Loss: 14/06/2021

Nature of Claim: TP

Claim
No: SNM21D203395/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YN5727J**

Make & Model: ISUZU NPR85UH5A, 3.0 D (M)

Engine No: 4JJ11J3846

Reg. Date: 11/07/2014 (Man. Year: 2014)

Chassis No: JAANPR85HE7100470

Colour: Blue

Odometer: 218261 km

Engine Capacity: 2999 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/85 R16

Rear Tyre Size: 195/85 R16

Front Left Side: Delium 4 mm

Rear Left Side: Bridgestone 4 mm

Front Right Side: Delium 4 mm

Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/06/2021

Date Inspected: 17/06/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Hs Automotives Pte Ltd (HQ)
2 KAKI BUKIT AVE 2
#01-15 KAKI BUKIT AUTOHUB
SINGAPORE 417921

Adjuster: Thevan Thomas Karthikesavan

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00
-\$3,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 01 Jul 2021)

Parts: N/A ISUZU NPR85UH5A 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YN5727J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >