

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI21006779/T1QCN2**Date:** 22/10/2021**REFERENCE**

|                              |                                               |                             |                    |
|------------------------------|-----------------------------------------------|-----------------------------|--------------------|
| Handling Insurer:            | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No:                  | DMHCSNW00008662000 |
| <b>Claimant Vehicle No :</b> | SMF7197J                                      | <b>Insured Vehicle No :</b> | SMC4487H           |
| Date of Loss:                | 03/05/2021                                    | Nature of Claim:            | TP                 |
|                              |                                               | Claim No:                   | SNM21D202560/C02   |

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SMF7197J</b>                   | Engine No:  | 36875367B38A15A   |
| Make & Model:               | BMW 216I, 1.5 (A)                 | Chassis No: | WBA6V12060ED05438 |
| Reg. Date:                  | 22/11/2018 (Man. Year: 2018)      | Odometer:   | 18832 km          |
| Colour:                     | Black                             |             |                   |
| Engine Capacity:            | 1499 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |             |                   |

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

**CONDITION OF TYRES**

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 205/55 R17    | Rear Tyre Size:  | 205/55 R17    |
| Front Left Side:  | Michelin 6 mm | Rear Left Side:  | Michelin 6 mm |
| Front Right Side: | Michelin 6 mm | Rear Right Side: | Michelin 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                     | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                     | 12,923.55         | 5,063.05          | 7,860.50          | 60.82         |
| Miscellaneous Items                       | 0.00              | 0.00              | 0.00              |               |
| Labour                                    | 2,955.00          | 2,220.00          | 735.00            | 24.87         |
| Paintwork Labour                          | 0.00              | 0.00              | 0.00              |               |
| Towing                                    | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>      | <b>15,878.55</b>  | <b>7,283.05</b>   | <b>8,595.50</b>   | <b>54.13</b>  |
| <b>Approved Total (Overridden) (\$\$)</b> |                   | <b>5,800.00</b>   |                   |               |
| <b>(\$\$)</b>                             | 15,878.55         | 5,800.00          | 10,078.55         | 63.47         |
| <b>+ GST 7.00/7.00% (\$\$)</b>            | 1,111.50          | 406.00            | 705.50            | 63.47         |
| <b>Nett Amount (\$\$)</b>                 | <b>16,990.05</b>  | <b>6,206.00</b>   | <b>10,784.05</b>  | <b>63.47</b>  |

**INSPECTION**

|                             |                          |                                                                                                                           |
|-----------------------------|--------------------------|---------------------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 17/06/2021               |                                                                                                                           |
| Date Inspected:             | 18/06/2021 Inspected At: | Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)<br>Blk 25 Kaki Bukit Road 4, #01-61 SYNERGY @ KAKI BUKIT<br>Singapore 417800 |
| Estimated Period of Repair: | 6.0 days                 |                                                                                                                           |

**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

|                      |                                                                                                                                                                              |                                                    |
|----------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------|
| <b>Part Source:</b>  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 22 Oct 2021)      |
| <b>Parts:</b>        | M1-MPV                                                                                                                                                                       | BMW 216I 1.5 (A) (Catalogue:Merimen Singapore 1.0) |
| <b>Labour:</b>       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                  |
| <b>Print Code:</b>   | (Unsubmitted, no print-code for SMF7197J)                                                                                                                                    |                                                    |
| <b>Validity:</b>     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                    |
| <b>Further Info:</b> | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                    |

### Recommended Parts

| No. | Qty | Part No. | Particulars                         | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT RH DOOR                      | Bent          | 1,725.00 FL | *1,725.00 FL |
| 2   | 1   |          | *FRONT RH DOOR OUTER HANDLE         | Distorted     | 142.50 FL   | *142.50 FL   |
| 3   | 1   |          | *FRONT RH DOOR GLASS OUTER MOULDING | Not Necessary | 165.00 FL   | *- FL        |
| 4   | 1   |          | *FRONT RH DOOR GLASS REGULATOR      | Not Necessary | 330.00 FL   | *- FL        |
| 5   | 1   |          | *FRONT RH ISE MIRROR                | Cut           | 642.00 FL   | *642.00 FL   |
| 6   | 1   |          | *FRONT RH DOOR HINGE TOP            | Not Necessary | 90.00 FL    | *- FL        |
| 7   | 1   |          | *FRONT RH DOOR HINGE BOTTOM         | Not Necessary | 69.00 FL    | *- FL        |
| 8   | 1   |          | *FRONT RH DOOR INNER BOARD (NPA)    | Not Necessary | 0.00 FL     | *- FL        |
| 9   | 1   |          | *FRONT RH DOOR TOP CHROME           | Not Necessary | 105.00 FL   | *- FL        |
| 10  | 1   |          | *REAR RH DOOR                       | Bent          | 1,725.00 FL | *1,725.00 FL |
| 11  | 1   |          | *REAR RH DOOR HINGE TOP             | Not Necessary | 90.00 FL    | *- FL        |
| 12  | 1   |          | *REAR RH DOOR HINGE BOTTOM          | Not Necessary | 90.00 FL    | *- FL        |
| 13  | 1   |          | *REAR RH DOOR GLASS OUTER MOULDING  | Not Necessary | 165.00 FL   | *- FL        |
| 14  | 1   |          | *REAR RH DOOR TOP CHROME            | Not Necessary | 105.00 FL   | *- FL        |
| 15  | 1   |          | *REAR RH DOOR GLASS REGULATOR       | Not Necessary | 480.00 FL   | *- FL        |
| 16  | 1   |          | *REAR RH DOOR INNER BOARD (NPA)     | Not Necessary | 0.00 FL     | *- FL        |
| 17  | 2   |          | *REAR RH DOOR GLASS                 | Not Necessary | 660.00 FL   | *- FL        |
| 18  | 1   |          | *REAR RH DOOR GLASS REGULATOR       | Not Necessary | 480.00 FL   | *- FL        |
| 19  | 1   |          | *REAR RH DOOR GLASS REGULATOR MOTOR | Not Necessary | 210.00 FL   | *- FL        |
| 20  | 1   |          | *RH SIDE SKIRT                      | Repair        | 345.00 FL   | *- FL        |
| 21  | 1   |          | *FRONT RH FENDER                    | Repair        | 570.00 FL   | *- FL        |
| 22  | 1   |          | *FRONT RH FENDER EMBLEM             | Necessary     | 75.00 FL    | *75.00 FL    |
| 23  | 1   |          | *REAR RH FENDER                     | Repair        | 2,250.00 FL | *- FL        |
| 24  | 1   |          | *REAR BUMPER                        | Repair        | 1,125.00 FL | *- FL        |
| 25  | 1   |          | *REAR BUMPER RH SIDE RETAINER       | Not Necessary | 78.00 FL    | *- FL        |
| 26  | 1   |          | *REAR BUMPER RH REFLECTOR           | Not Necessary | 48.00 FL    | *- FL        |
| 27  | 1   |          | *REAR RH TAILLAMP                   | Not Necessary | 390.00 FL   | *- FL        |
| 28  | 1   |          | *FRONT RH DOOR RUBBER               | Necessary     | 202.50 FL   | *202.50 FL   |
| 29  | 1   |          | *REAR RH DOOR RUBBER                | Necessary     | 202.50 FL   | *202.50 FL   |
| 30  | 1   |          | *FRONT RH DOOR STICKER              | Necessary     | 60.00 FS    | *60.00 FS    |
| 31  | 1   |          | *REAR RH DOOR STICKER               | Necessary     | 60.00 FS    | *60.00 FS    |
| 32  | 1   |          | *FRONT RH WHEEL RIM                 | Cut           | 350.00 FS   | *350.00 FS   |
| 33  | 1   |          | *REAR RH WHEEL RIM                  | Cut           | 350.00 FS   | *350.00 FS   |
| 34  | 1   |          | *FRONT RH TYRE                      | Not Necessary | 250.00 FS   | *- FS        |
| 35  | 1   |          | *REAR RH TYRE                       | Not Necessary | 250.00 FS   | *- FS        |
| 36  | 1   |          | *REAR BUMPER SENSOR                 | Not Necessary | 300.00 FS   | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                 |
|------------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>14,179.50</b> | <b>5,534.50</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | 1,255.95         | 471.45          |
| <b>Total Parts (\$\$)</b>                                  | <b>12,923.55</b> | <b>5,063.05</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                                                                                                          | Lab.Type | Repairer's      | Amount          |
|---------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                                                                                                                                      |          |                 |                 |
| 1                               | TO RESET POWER WINDOW                                                                                                                                                                                | New      | 120.00          | 80.00           |
| 2                               | TO REMOVE AND REFIT REAR BUMPER SENSOR                                                                                                                                                               | New      | 80.00           | 30.00           |
| 3                               | TO COMPUTER RESET AND RE-PROGRAM ALL FAULT CODE                                                                                                                                                      | New      | 350.00          | 200.00          |
| 4                               | TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS,REPLACE DAMAGED PARTS                                                                                                       | New      | 250.00          | 0.00            |
| 5                               | TO TRANSFER DOOR                                                                                                                                                                                     | New      | 80.00           | 80.00           |
| 6                               | TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS                     | New      | 950.00          | 800.00          |
| 7                               | TO CARRY-OUT BODY CAVITY PRESERVATION                                                                                                                                                                | New      | 80.00           | 30.00           |
| 8                               | TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS                                                                                                                                                | New      | 45.00           | 0.00            |
| 9                               | TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE | New      | 1,000.00        | 1,000.00        |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                                                                                                      |          | <b>2,955.00</b> | <b>2,220.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >